## Instructions for Removing the Dogging Assembly From a Jackson 1285

Reference Drawing	Instructions
1	Remove each base cover
6	Remove each extruded cover
	On active side, remove
	(1) 8/32 x 1 cap screw
	(1) 12/24x1 1/4 phillister screw
	On the inactive side, remove a single 1/4 20 round head screw
	Panic is now free
2	Remove active lift assembly with single 6-32 screw
5	Remove each plastic cap from push bar,
	Slide push bar towards inactive side until 2 rollers are exposed.
3	Remove each roller
	Remove push bar by sliding it toward active side
4	Remove 4ea. 4-40 screws
	Replace dogging assembly

