


2008, 2009

For a time had recessed spring cover

1.75 coils

No longer available




Several revisions, some with cover, some without.

Stop plate had several revisions

Note one leg crosses over the coil


14-5400-1061



July 2013 - Ongoing

3.75 coils

Engineering made some design changes to the rose support assembly and the return spring that went into production in July of 2013. This spring does not work on locks made before this date.



14-5401-1077