

4" DOOR RAIL PREPARATION for CRL 777SL

CNC Program 4011

Lock modification required; Spacer NOT required; Special side hole position per dwg.

INSPECTION: Lock FIT. NO dimensional inspection required.

