


Gap Solution for Excessive Fire Door and Frame Clearances — 90 Minute

UL Certified Solution for Fire doors with Excessive clearance between door and frame over 1/8", up to 5/16"

Requires installation of **ALL** components below:




9945

Steel Stop Extender

16 Gauge , Gray Primer Finish

Furnished with #10 X 1" TEK SMS

Patent No.: US9,273,510B2



9400

Gray

9400DKB


Brown

NGP-Edge® Intumescent Seal with PVC cover

Self-Adhesive - specifications on page G9



Anti-Microbial



5075B

Brown

5075CL

Clear

Self-Adhesive TPE Seal



*Anti-Microbial not available in clear

Ordering Information:

GAP90™ Includes 9945, 9400, 5075CL

GAP90DKB™ Includes 9945, 9400DKB, 5075B

Available in 36", 48", 84" and 96" lengths



90 minute rated UL Certified Miscellaneous Fire Door Accessory UL10B and UL10C wood or hollow metal fire doors

An NGP strike shim 9275 or 9225 is also required for proper latchbolt engagement

Parallel arm closers require mounting bracket 600D-28

INSTALLED VIEW

