

Installation and Assembly - Adapter Bracket for VESA® 200 x 200 Screens

Model: PLP-V2X2


IMPORTANT! Read entire instruction sheet before you start installation and assembly.

Maximum Load Capacity : 125 lbs (57 kg)



Parts List

Description	Qty.	Part #
A adapter bracket	1	202-1505
B M6 x 12mm socket pin screw	4	520-1050
C 4mm allen wrench	1	560-9646
D M6 x 20mm socket pin screw	4	520-9554
E M8 x 10mm socket pin screw	4	520-1706
F M4 x 8mm sock pin serrated washer head screw	4	510-1005
G #10 washer	4	540-9400
H M4 x 12mm socket pin serrated washer head screw	4	510-1079
I M5 x 10mm socket pin screw	4	520-1063




Used with specific mounts only

Some parts may appear slightly different than illustrated.

⚠ WARNING

- Do not overtighten! Overtightening may cause permanent damage to the screen. Torque to 26-35 in • lb (30-40 kg • cm).

- Begin with shortest length screw (E or F), hand thread through adapter plate into screen as shown below. Screw must make at least three full turns into screen insert and fit snug into place. Do not over tighten. If screw cannot make three full turns into screen insert, select a longer length screw (B, D or H). Repeat for remaining holes.



#10 washer (G) is only to be used with M4 x 8 mm socket pin serrated washer head screw (F), M4 x 12 mm socket pin serrated washer head screw (H) or M5 x 10mm socket pin screw (I).

Washer goes between screw and adapter plate.

