


Restore Lost Fire Rating

Maximum 0.5" (12.7mm) clearances allowed at the bottom of fire-rated doors do not leave much room for error. Fire ratings lost when installation or alignment problems cause larger clearances can be restored using these INTUMET™ solutions, without the costs of structural changes or door replacement.


20-Minute Rating



#339FS AA
#339FS D

Restore for 20 minute fire-rated wood doors and metal doors with excessive undercut up to 1.250". ITS-listed to positive pressure UBC 7-2 1997.


90-Minute Rating




#521FS AA

Restore for 90 minute fire-rated metal doors with excessive undercut up to 1.250". Tested under UL 10C, UBC 43-2, NFPA 252 standards by an Independent laboratory.


Other products with Intumescent



#59FS A




#253FS A




#111FS A

FLO Option Door Sweeps

Door sweeps with FLO Option are designed with neoprene or brush seals that are notched and overlapped. This feature allows air to flow while blocking light.



#111A-FLO




#3546A

#3546A-FLO

#3544A Brush insert (not shown)

#3544A-FLO



#3546A-FLO