



Restore Lost Fire Rating


Maximum 0.5" (12.7mm) clearances allowed at the bottom of fire-rated doors do not leave much room for error. Fire ratings lost when installation or alignment problems cause larger clearances can be restored using these INTUMET™ solutions, without the costs of structural changes or door replacement.

20-Minute Rating






Restore for 20 minute fire-rated wood doors and metal doors with excessive undercut up to 1.250". ITS-listed to positive pressure UBC 7-2 1997.

90-Minute Rating



Restore for 90 minute fire-rated metal doors with excessive undercut up to 1.250". Tested under UL 10C, UBC 43-2, NFPA 252 standards by an independent laboratory.

Other products with Intumescent



FLO Option Door Sweeps

Door sweeps with FLO Option are designed with neoprene or brush seals that are notched and overlapped. This feature allows air to flow while blocking light.

