

| OEM (MPN) Cross Reference to Arrco Model: AA20KP-BFV |                  |                  |                 |
|------------------------------------------------------|------------------|------------------|-----------------|
| 918561                                               | 4TWR3024B1000AA  | GSZ130241BB      | YHE24B21SA      |
| 918868                                               | 4TWX6024E1000AA  | GSZ130241BC      | YHJF24S41S1A    |
| 919606                                               | 4TWZ0024A1000AC  | GSZ130241BD      | ZP20K3E-PFV     |
| 921422                                               | 55-102045-01S    | GSZ130241CA      | ZP20K4E-PFV     |
| 921423                                               | 55-102045-104S   | GSZ130241CB      | ZP20K5E-PFV     |
| 100040-02                                            | 55-102045-148S   | GSZ140241K       | ZP20K6E-PFV     |
| 101995-02                                            | 55-102045-24S    | H84B183ABCA      | P021-21210P     |
| 10T60                                                | 550ANX024        | JS4BD024KA       | RPH13410A24J    |
| 113ANA024                                            | 550ANX024000AAAA | JS4BE024KA       | S1-01504141004  |
| 113ANW024                                            | 622437R          | JS6BD024K        | S1-01504781001  |
| 114ANA024                                            | 622624R          | JS6BF024K        | VR8GD024K072C   |
| 114CNA024                                            | 622706           | JS6QD024KA       | ZP20K5E-PFV-130 |
| 116BNA024                                            | 650ANX024000     | JT4BD024K        | ZP20K5E-PFV-230 |
| 123ANA024                                            | 663GJX024000     | JT4BE024         | ZP20K5E-PFV-250 |
| 13ACX024230                                          | 97M53            | ML14XC1S024      | ZP20K5E-PFV-800 |
| 13AJL24A01                                           | ANX130241AA      | N4A324AKB200     | ZP20K5E-PFV-830 |
| 13AJM24A01                                           | ANX130241AB      | N4A324AKC100     | ZP20K5E-PFV-930 |
| 13AJN24A01                                           | APA020KAA        | N4H324AKA200     | ZP20K5E-PFV-950 |
| 13HPP24AP                                            | APB020KAA        | N4H324CKA100     | ZP20K3E-PFV-130 |
| 13HPX024230                                          | APG1324045M41CA  | N4H424AKB200     | ZP20K3E-PFV-230 |
| 13PJL24A01                                           | APG1324070M41CA  | NS4BD024K        | ZP20K3E-PFV-250 |
| 14ACX024230                                          | ASX130241        | NT4BE024K        | ZP20K3E-PFV-800 |
| 14ACXS024230                                         | ASX140241        | NT4QD024K        | ZP20K3E-PFV-830 |
| 14AJL24A01                                           | ASX140251        | NXH524GKA100     | ZP20K3E-PFV-930 |
| 14AJM24A01                                           | ASX160241        | P02121210P       | ZP20K3E-PFV-950 |
| 14AJM25A01                                           | ASZ140241        | P032-1926        | ZP20K4E-PFV-130 |
| 14HPX024230                                          | CA16NA02400      | P7RD024KA        | ZP20K4E-PFV-230 |
| 14PJM24A01                                           | CH13NA02400      | PA14NC024000AAAA | ZP20K4E-PFV-250 |
| 15PJL24A01                                           | CH14NA02400      | PH13NA024000     | ZP20K4E-PFV-800 |
| 213ANA024                                            | CH14NB02400      | PH14NB024000     | ZP20K4E-PFV-830 |
| 213ANA024000                                         | COM07336         | PH15NB024000     | ZP20K4E-PFV-930 |
| 213BNA024                                            | COM07337         | PHD324000K000C1  | ZP20K4E-PFV-950 |
| 213BNA024000                                         | COM08454         | PHJ324000K000    | ZP20K6E-PFV-130 |
| 213BNW024                                            | COM09525         | PSH4BD024K       | ZP20K6E-PFV-230 |
| 213BNW024000                                         | COM09698         | PY3GNAA24060NA   | ZP20K6E-PFV-250 |
| 215BNA024                                            | COM09279         | Q5RD024K         | ZP20K6E-PFV-800 |
| 223ANA024000                                         | COM10014         | Q7RE024K         | ZP20K6E-PFV-830 |
| 24ABA324A00300                                       | COM10522         | R4A324AKA200     | ZP20K6E-PFV-930 |
| 24ABB324A00310                                       | COM11524         | R4H324GKB100     | ZP20K6E-PFV-950 |
| 24ABC624A00300                                       | CSH4BD024K       | RA1424AJ1NA      | ZP20KAE-PFV-130 |
| 24ACC424A00300                                       | CXA624GKA100     | RA1624AJ1NA      | ZP20KAE-PFV-230 |
| 25HBA324A300                                         | CXH524GKA100     | RANL024JAZ       | ZP20KAE-PFV-250 |
| 25HBB324A00300                                       | DP19A-YY1-LB     | RAPL024J         | ZP20KAE-PFV-800 |

|                 |                  |                 |                 |
|-----------------|------------------|-----------------|-----------------|
| 25HBC324A00300  | DP19A-YZ1-A      | RP1424AJ1NA     | ZP20KAE-PFV-830 |
| 25HBC524A00300  | DP20A-YZ1-LC     | RP1424FJ1NA     | ZP20KAE-PFV-930 |
| 25HCA324A00300  | DP20A-ZZ1-A      | RPNL024JAZ      | ZP20KAE-PFV-950 |
| 25HCE424A00300  | DP22A-ZZ1-KA     | RPQL024J        | APG020KA        |
| 38EYG024        | DS4QD024KC       | RQPWB024J       | APA020KA        |
| 38EZA024        | DT4BD024K        | RQPWB025J       | APB020KA        |
| 38EZG024        | ES4BD024K        | S101504141004   | ZP21K5E-PFV     |
| 38TXA024        | ES6BF024K        | S101504781001   | ZP22KCE-PFV     |
| 38YDB024        | ET4BD024K        | S101504076004   | H80J183ABC      |
| 48ES-024060311  | ET4BE024K        | SBA020CICPZ     | H80J223ABC      |
| 4AC13B24P       | FB4CNP024L00AAAA | SSX140241       | H81J223ABC      |
| 4AC13L24P       | FS4BC024K        | SSZ140241       | H81J22BABC      |
| 4AC14B24P       | FT4BD024K        | SSZ160241       | H82J193ABC      |
| 4AC14L24P       | FT4BE024K        | SXA016C1BPZ     | H82J19BABC      |
| 4HP13B24P       | GPG1324045M41CA  | TCJD24S41S3A    | H82J213ABC      |
| 4HP13L24P       | GPG1324070M41CA  | THJR24S41       | H82J21BABC      |
| 4HP14B24P       | GPH1324H41       | TPA020B1RPZ     | H82J223ABC      |
| 4HP14L24P       | GPH1424H41       | UANL024JAZ      | H82J22BABC      |
| 4SHP13LB124P    | GR8GD024K072C    | VS4BD024KB      | H83B193ABC      |
| 4SHP13LE124P    | GSX130241AB      | VSX130241       | H89B193ABC      |
| 4SHP14LB124P    | GSX130241BA      | VSZ130241       | H89B19BABC      |
| 4SHP14LE124P    | GSX130241DA      | VT4BD024K       | H89B223ABC      |
| 4TTR2024A1000AA | GSX140241KA      | VT4BE024K       | H89B22BABC      |
| 4TTR4024L1000BA | GSX140251KA      | WJH324000KTP0A1 | T81J195CBC      |
| 4TTR4025L1000BA | GSX160241FA      | XC13024230      | T89B194CBC      |
| 4TWB4024G1000BA | GSZ130241AB      | XC14024230      | APA022K         |
| 4TWR2024A1000AA | GSZ130241AC      | YCE24B21HA      |                 |
| 4TWR3024A1000AA | GSZ130241BA      | YCJD24S41S1A    |                 |