

**OEM (MPN) Cross Reference to Arrco Model: AA54KP-BFV**

|                 |                  |                 |                 |
|-----------------|------------------|-----------------|-----------------|
| 918873          | 4TTB3060D1000BA  | JT4BD060K       | ZP54K3E-PFV-130 |
| 921468          | 4TTR3060A1000AA  | JT4BE060        | ZP54K3E-PFV-230 |
| 100040-12       | 4TTR3060D1000AB  | MOVA60HN1M      | ZP54K3E-PFV-250 |
| 101995-07       | 4TWB3060B1000CA  | MOVB60HN1M      | ZP54K3E-PFV-800 |
| 113ANC060       | 4TWR2060A1000AA  | N4H360AKB400    | ZP54K3E-PFV-830 |
| 120U1301        | 4TWR3060A1000AB  | NS4BD060K       | ZP54K3E-PFV-930 |
| 120U2042        | 55-102045-13S    | NT4BE060K       | ZP54K3E-PFV-950 |
| 120U2062        | 550ANX060        | NT4QD060K       | ZP54K4E-PFV-130 |
| 13ACX060230     | 550ANX060000AEAA | P0215324P       | ZP54K4E-PFV-230 |
| 13HPX060230     | 622588R          | P0215422        | ZP54K4E-PFV-250 |
| 13PJL60A01      | 622747           | P7RD060KA       | ZP54K4E-PFV-800 |
| 18W53           | 633GJX060000     | PH13NA060000    | ZP54K4E-PFV-830 |
| 18W54           | 650ANX060000     | PSH4BD060K      | ZP54K4E-PFV-930 |
| 213ANA060       | 663GJX06000      | Q7RE060K        | ZP54K4E-PFV-950 |
| 213ANA060000    | 97M58            | RANL060JAZ      | ZP54K6E-PFV-130 |
| 213BNA060       | ABA054KAA        | RPNL060JAZ      | ZP54K6E-PFV-230 |
| 213BNA060000    | ABA054KAC        | RQNLB060JK      | ZP54K6E-PFV-250 |
| 213BNW060       | ABA054RAB        | RQNMA060JK      | ZP54K6E-PFV-800 |
| 213BNW060000    | ABA054WAB        | RQPWB060J       | ZP54K6E-PFV-830 |
| 223ANA060000    | CH13NA06000      | RTC60C2C        | ZP54K6E-PFV-930 |
| 25HBA360A00300  | CH14NA06000      | SPA054A1RPZ     | ZP54K6E-PFV-950 |
| 25HBA424A310    | CH14NB06000      | SPA057A1RPZ     | ZP54KAE-PFV-130 |
| 25HBA460A00300  | COM06919         | SXA054B1BPZ     | ZP54KAE-PFV-230 |
| 25HBB360A00300  | COM07334         | UANL060JAZ      | ZP54KAE-PFV-250 |
| 25HBC360A00300  | COM08809         | VT4BD060K       | ZP54KAE-PFV-800 |
| 25HCB360A00500  | COM09757         | VT4BE060K       | ZP54KAE-PFV-830 |
| 265ANA060000    | COM10917         | XC13060230      | ZP54KAE-PFV-930 |
| 38EYG060        | CSH4BD060K       | XP13060230      | ZP54KAE-PFV-950 |
| 38EZA060        | CXH260AKC1       | ZP54K5E-PFV     | ABA054KA        |
| 38TPA060        | DT4BD060K        | ZP54K3E-PFV     | ABA051KA        |
| 38TXA060        | ES4BD060K        | ZP54K6E-PFV     | HRH054U1        |
| 38YXA060        | ET4BD060K        | ZP54K7E-PFV     | ABA054K         |
| 4A7A4060A1000AA | ET4BE060K        | P021-5324P      | H83R543ABC      |
| 4A7B3060D1000AA | FS4BD060KB       | P021-5422       | H89A543CBC      |
| 4HP13B60P       | FT4BD060K        | ZP54K5E-PFV-130 | XND540HA        |
| 4HP13L60P       | FT4BE060K        | ZP54K5E-PFV-230 | XND540HE        |
| 4SHP13LB160P    | FVBN0060         | ZP54K5E-PFV-250 | XND540HU        |
| 4SHP13LC160F    | GSZ130601AB      | ZP54K5E-PFV-800 | H83R563ABC      |
| 4SHP13LC160T    | HRH054U1LP6      | ZP54K5E-PFV-830 |                 |
| 4SHP13LE160P    | HRH061T1LP6      | ZP54K5E-PFV-930 |                 |
| 4SHP14LB160P    | JS4BD060KA       | ZP54K5E-PFV-950 |                 |