

NADAguides Value Report 5/20/2018

2002 Kountry Star Fifth Wheel Series M-34DSSK (*)

Values

	Suggested List Price	L ow Retail	Average Retail
Base Price	\$51,964	\$8,250	\$9,950
Options (Change)			
15,000 BTU Central/Ducted		\$215	\$260
8 cu. ft.		\$355	\$430
Microwave Oven		\$30	\$35
Microwave/Hood Combo		\$105	\$125
Water Heater 10 Gallon Gas/Elec		\$55	\$65
Air Assisted Suspension		\$85	\$100
AM/FM/CD Stereo		\$60	\$75
TV Antenna w/Booster		\$20	\$25
Electric Front Jacks/Fifth Wheel Trailers		\$85	\$100
Awning 15' - 16' (Each)		\$140	\$170
Celing Fan		\$25	\$30
Luggage Rack and Ladder		\$25	\$30
Power Roof Vent		\$35	.\$45
Power Slide-Out Room (Bedroom) (Each)		\$315	\$380
Skylight	terana di manakerkeranda taztu an totak kekendikazan keperintakasa.	\$50	\$60
Total Price	\$51,964	\$9,850	\$11,880

Value Type Definitions

Suggested List — The value listed reflects the approximate price of the unit when it is brand new. The prices listed are furnished by the manufacturer and are assumed to be correct. The list price does not include freight charges.

Low Retail Value — A low retail unit may have extensive wear and tear. Body parts may have dents and blemishes. The buyer can expect to invest in cosmetic and/or mechanical work. This vehicle should be in safe running order. Low retail vehicles usually are not found on dealer lots. Low retail is not a trade-in value.

Average Retail Value — An average retail vehicle should be clean and without glaring defects. Tires and glass should be in good condition. The paint should match and have a good finish. The interior should have wear in relation to the age of the vehicle. Carpet and seat uphotstery should be clean, and all power options should work. The mileage should be within the acceptable range for the model year.