N 88°14'15" E 2,609.85' (c)

North line, SE 1/4, Sec. 31-T38N-R15E 1,304.93' (c) N 88°14'15" E NW Cor, E 1/2, SE 1/4,-/ Sec. 31 - T38N - R15E ∽*NW* Cor, SE 1/4, LEGAL DESCRIPTION (11.00-acre Parcel) **BOUNDARY SURVEY** Sec. 31 - T38N - R15E Stone Fnd. (-3.0) Part of the East Half of the Southeast Quarter Section 31, Township 38 North, Range 15 Stone Fnd. (-3.0) Part of the SE 1/4 in Sec. 31, T 38 N, R 15 E East, Clear Lake Township, Steuben County, Indiana, being part of a 19.962-acre parcel depicted on Gouloff-Jordan Surveying & Design Survey #20220038, dated March 28, Clear Lake Township, Steuben County, IN 2022, described as follows: 7950 County Road E. 400 N., Fremont, IN 46737 Commencing at a railroad spike at the Southeast corner of the Southeast Quarter of said SURVEYOR'S REPORT GOULOFF-JORDAN SURVEYING AND DESIGN, INC. Section 31; thence South 88 degrees 34 minutes 46 seconds West (bearings based on Indiana East State Plane Coordinate System (NAD'83)(2011)), on the South line of the FOR THE EXCLUSIVE USE OF: Richmond DATE: March 28, 2022 East Half of said Southeast Quarter, a distance of 373.95 feet to a mag nail with Gouloff-Jordan Surveying & Design, Inc. ID ring at the Point of Beginning; thence North JOB NO: 20220038 02 degrees 41 minutes 42 seconds West, parallel with the East line of said Southeast Quarter, a distance of 185.00 feet to a 5/8" rebar capped "GOU"; thence North 40 degrees This report and the accompanying survey plat have been prepared in accordance with Title 865, Article 1, Rule 00 minutes 00 seconds West, 135.00 feet to a 5/8" rebar capped "GOU"; thence North 75 12, Sec 1-29, and all amendments thereto, of the Indiana Administrative Code, which establishes the minimum degrees 00 minutes 00 seconds West, 210.00 feet to a 5/8" rebar capped "GOU"; thence standards for the practice of land surveying. North 45 degrees 00 minutes 00 seconds West, 300.00 feet to a 5/8" rebar capped "GOU"; thence North 02 degrees 45 minutes 00 seconds East, 94.00 feet to a 5/8" rebar Monuments set are 5/8-inch round by 24-inch long steel rebars with yellow plastic caps stamped 'GOULS capped "GOU" on the North line of a 14.99-acre parcel described in Document 29500017" and are set flush with the ground surface unless otherwise noted. Found monument types and #21100509, as found in the Office of the Recorder of Steuben County, Indiana; thence their depths are shown on the survey drawing. South 88 degrees 34 minutes 46 seconds West, on said North line, being parallel with the South line of the East Half of said Southeast Quarter, 465.25 feet to a mag nail on the Title report was not provided at time of survey. A title search could reveal easements or rights of way not West line of the East Half of said Southeast Quarter; thence South 02 degrees 26 minutes shown on the survey drawing. 03 seconds East, on said West line, 661.04 feet (661.10 feet recorded) to a railroad spike at the Southwest corner of the East Half of said Southeast Quarter; thence North 88 The subject survey is a retracement and subsequent split of a real estate described in Document degrees 34 minutes 46 seconds East, on the South line of the East Half of said Southeast #21100509 as found in the Office of the Recorder of Steuben County, Indiana. Said real estate is described as Quarter, a distance of 943.26 feet to the Point of Beginning, containing **11.00 acres**, more Parcel 1, being a 14.99-acre parcel and Parcel 2, being a 5.00-acre parcel. Said 5.00-acre parcel also being or less, and subject to easements and rights-of-way of record. depicted on a Moody Bevington Shirmeyer and Associates (MBS) Survey #0797-01, dated August 11, 1999. The subject parcel(s) were also part of recorded Gouloff-Jordan survey#20030358-c, dated October14, 2008 in Doc. #09120735. The Gouloff-Jordan survey of Sections 31 and 32 occurred circa 2003. CONTROLLING MONUMENTS: SE Corner SE ¹/₄ - Sec. 31, T38N, R15 E - Railroad spike found (-0.2') SW Corner East ½ - SE ¼ - Sec. 31, T38N, R15 East - Railroad Spike found (-0.1) NE Corner SE ¼ - Sec. 31, T38N, R15 E - 5/8" rebar capped "GOU" (-0.0') NW Corner East ½ - SE ¼ - Sec. 31, T38N, R15 East - ½" rebar (+0.4) THEORY OF LOCATION: Though the geometry reflected on the subject deed of record (Doc. #21100509) and the above-mentioned MBS survey proofed closure, said geometry does not fit the accepted Section monuments as reflected in the above-mentioned Gouloff-Jordan survey of Section 31. Johns \geq Subsequent to the Gouloff-Jordan survey of the subject East ½ of the SE ¼ of Section 31, LOJEK Doc. # 20060090 Surveying (Job #0708-21) performed a survey of a 37.19-acre parcel (Doc. #21100510) lying immediately North of and adjacent with the subject parcel. The LOJEK survey seems to have held the monuments reflected on the Gouloff-Jordan survey of the East 1/2 of the SE 1/4 of Section 31. Analyzing the recorded deed geometry, it seems that the intent of the MBS surveys was to split the Southerly 20 acres of the East ½ of the subject SE ¼. It would seem that the North line of the subject parcel –Mag Nail Fnd. (0.0) was meant to be 661.10 feet North of and parallel with the South line of the SE ¼ of Section 31. / 5/8" Rebar set with "GOU" cap The NE corner of the subject parcel was thus established on the East line of the SE ¼, a distance of 661.10 (20.0'E) feet North thereof. The North line of the subject parcel was then established parallel with said South line. The 1/4, NW corner of the subject parcel was established at the intersection point of said parallel line with the West line S 88°34'46" W **465.25' (c)** of the East $\frac{1}{2}$ of said SE $\frac{1}{4}$. L Ы The common line between the 11.00-acre parcel and 5.163-acre parcel was established just Easterly of an existing cultivated field line per the owner's request (see survey drawing). The common line between the 5.163-acre parcel and the 3.80-acre parcel was established approximately 10 feet east of the eastern edge of N, an existing gravel drive (see survey drawing). Ξ The uncertainty in the lines and corners found or established by this survey are as follows: (A) Availability and condition of reference monuments: Reference monuments found on the subject property and on adjacent properties are shown on the survey drawing. Due to variations in the type of said reference monuments and/or variations depicted on the survey drawing as "measured" versus "recorded" angular or distance measurements, uncertainty in said reference monuments is 0.67 Feet North-South and 4.40 feet East-West. Ш (B) Occupation or possession lines: No uncertainty was created by visible occupation lines (fences, hedge rows, etc.) that were evident at the time S of the survey. \sim \sim 3 (C) Clarity or ambiguity of the record description and or adjoiner's descriptions: ad See above referenced "Theory of Location" 2 Ro 11.00 Ac. The Relative Positional Precision of this survey falls under the classification of a "Rural" survey. Random errors in measurement = 0.26 feet (79 millimeters) plus 200 parts per million as specified in Section 7 of said Rule 12. ounty SURVEYOR'S CERTIFICATION This survey was performed by, or under the responsible direction of the undersigned registered \mathbf{O} land surveyor and to the best of said registered land surveyor's knowledge and belief, said survey was executed according to the applicable survey requirements of 865 IAC-1-12-1 thru 29. Field work for this survey was performed on February 16, 2022. DATED THIS 28h DAY OF MARCH, 2022. GISTE No.29500017 STATE OF WOIANA. Timothy C. Gouloff, R.L.S. 2950001 IND SURY "I affirm, under the penalties for perjury, that I have taken reasonable care to redact each Social Security Number in this document, unless required by law." Timothy C. Gouloff 20' RW line 1,3017.05' (c) N 88°34'40" E County Road E. 400 N. South line, SE 1/4, Sec. 31-T38N-R15E S 88°34'46" W 2,634.26' (c) -SW Cor, E 1/2, SE 1/4, (Indiana State Plane Corrdinate System NAD83/2011) Sec. 31 - T38N - R15E RR Spike Fnd. (0.0) - SW Cor, SE 1/4, Sec. 31 - T38N - R15E RR Spike Fnd. (0.0)

