2015 building condition survey Lindenhurst UFSD

Draft number 1

Jul-16

JAG Architect PC

Description of Work	Priority A	Priority B	Priority C	Comments
Electrical Service	\$190,000.00			replace existing 1600 amp service
Playground Safety Surface	\$22,000.00			Provide ADA surface below swings
Asphalt Pavement	\$106,400.00			Repave Main Parking Lot
Sidewalks	\$45,000.00			Replace Sections of Sidewalk
Exterior Masonry	\$35,000.00			Misc Exterior Brick Repointing
Chimney	\$15,000.00			Brick Repointing and Replace Chimney Cap
Windows	\$2,693,000.00			Replace all windows and Upper Transoms
Ceiling Replacement	\$497,080.00			Replace all concealed spline ceilings
Roofing	\$1,332,695.00			Replace Entire Roof - No longer Under Warranty
Interior Door and Hardware	\$85,000.00			Replace Locksets with High Security/partial door replacement
Stage Lighting	\$185,000.00		a)	Replace Stage Lighting - Asbestos Wiring
Plumbing/Bathrooms	\$1,130,208.00	-		Replace original Multi-Stall Toilets, classroom sinks and cabinets
Air Handling & Ventilation	\$1,480,000.00			Replace all Unit Ventilators, and Provide Mechanical fresh air ventilation to all student/staff occupied spaces
Temperature Controls	\$100,000.00			Replace existing Temperature Controls
Handicapped Accessibilty	\$465,000.00			Provide ADA toilets - Faculty, Nurse, Drinking Fountains etc.
Construction Cost Totals	\$8,381,383.00			
Note: Above costs are Constructions and Constructions and Constructions and Constructions and Constructions and Constructions are Constructions and Constructions and Constructions are Constructed and Constructions and Constructions are Constructed and Constructions and Constructions are Constructed and Constructed and Constructions are Constructed and Cons	ction(hard costs) only and Construciton cost	- 18% Soft cost contingencies	ts and Contingency : to cover unforseen	should be added to cover the following - A/E fees, testing conditions which may arise throughout the project.

Description of Work	Priority A	Priority B	Priority C	Comments
Playground Safety Surface	\$48,000.00			Provide ADA surface below playground
Playground	\$85,000.00			Repave Asphalt play area
Fuel Oil Tank	\$10,000.00			Replace cracked tank slab
Sidewalks	\$45,000.00			Replace Sections of Sidewalk - Caulk transition from
				sidewalk to building
Exterior Masonry	\$40,000.00			Misc Exterior Brick Repointing
Chimney	\$5,000.00			Brick Repointing
Ceiling Replacement	\$128,000.00			Replace all concealed spline ceilings/metal pan in
				kitchen
Roofing	\$1,767,500.00			Replace Entire Roof except 3 classroom addition - No
				longer Under Warranty
Interior Door and Hardware	\$66,000.00			Replace Locksets with High Security/partial door
				replacement
Plumbing/Bathrooms	\$180,000.00			Replace original Multi-Stall Toilet - North wing
Air Handling & Ventilation	\$740,000.00			Replace all Unit Ventilators, and Provide Mechanical
				fresh air ventilation to all student/staff occupied spaces
Boiler Replacement	\$525,000.00			Replace boilers - burners shall be re-used
Temperature Controls	\$125,000.00			Replace existing Temperature Controls
Handicapped Accessibilty	\$465,000.00			Provide ADA toilets - Faculty, Nurse, Drinking Fountains
			ū	and access to upper rooms behind cafeteria etc.
Fire Alarm System	\$125,000.00			Replace fire alarm and smoke system

Construction Cost Totals	\$4,354,500.00				
N-1-Al		400/ 5 5:			
					dded to cover the following - A/E fees, testing
rees, Civi, Legal Fees, Pfillting a	and Construction cost	contingencies	to cover uniors	en conditions v	which may arise throughout the project.
			T	T	

Bower Elementary School

Description of Work	Priority A	Priority B	Priority C	Comments
Electrical Service	\$135,000.00			Replace existing electrical service
Asphalt Pavement	\$210,000.00			Repave Asphalt play area and West parking lot
Sidewalks	\$20,000.00			Replace cracked sidewalks
Playgrounds	\$185,000.00	10.00		Replace existing play Structure and surfacing
Exterior Masonry	\$80,000.00			Misc Exterior Brick Repointing
Chimney	\$25,000.00			Brick Repointing
Windows	\$645,000.00			Replace all windows
Roofing	\$1,728,695.00			Replace Entire Roof - No longer Under Warranty
Ceilings	\$984,000.00		11	Replace all concealed spline ceilings/metal pan in
				kitchen - Replace plaster ceilings or create access panels
				to inspect structural roof members - extensive roof
				leaks
Interior Doors and Hardware	\$100,000.00			Replace Locksets with High Security/partial door
				replacement
Hot Water Heater	\$50,000.00			Replace existing hot water heater
Plumbing Fixtures	\$850,000.00			
а				Replace Multi-Stall toilets, Classroom sinks and cabinets
Boiler and Burners	\$750,000.00			Replace Boilers and Burners
Air Handling and Ventilation	\$3,300,000.00			Replace all Unit Ventilators, and Provide Mechanical
				fresh air ventilation to all student/staff occupied spaces -
				convert system from steam to hot water
Temperature Controls	\$125,000.00			replace existing temperature control system
Handicapped Assessibility	\$125,000.00			Provide ADA toilets - Faculty, Nurse, Drinking Fountains
6				and access to upper rooms behind cafeteria etc.
Construction Cost Totals	\$9,312,695.00			

		nditions which may arise throughout the project.

Description of Work	Priority A	Priority B	Priority C	Comments
Electrical Service	\$175,000.00			Replace existing electrical service
Sidewalks	\$10,000.00			Replace cracked sidewalks
Playgrounds	\$78,000.00			Replace existing playground surfacing
Exterior Masonry	\$70,000.00			Misc Exterior Brick Repointing
Chimney	\$6,000.00			Brick Repointing
Windows	\$2,626,000.00			Replace all windows
Roofing	\$2,464,980.00			Replace Entire Roof - No longer Under Warranty
Ceilings	\$309,075.00			Replace all concealed spline ceilings/metal pan in
				kitchen
nterior Doors and Hardware	\$72,400.00			Replace Locksets with High Security/partial door
		-		replacement
Plumbing Fixtures	\$1,134,000.00			
				Replace Multi-Stall toilets, Classroom sinks and cabinet
Air Handling and Ventilation	\$1,280,000.00			Replace all Unit Ventilators, and Provide Mechanical
				fresh air ventilation to all student/staff occupied space
				,
Fire Alarm System	\$125,000.00			Replace fire and smoke alarm system
Temperature Controls	\$50,000.00			Upgrade controls on H & V's and AHU's
Handicapped Assessibility	\$400,000.00			Provide ADA toilets - Faculty, Nurse, Drinking Fountains
				and access to upper rooms behind cafeteria etc.
Construction Cost Totals	\$8,800,455.00			

Description of Work	Priority A	Priority B	Priority C	Comments
Electrical Service	\$125,000.00			Replace existing electrical service
Sidewalks	\$25,000.00			Replace cracked sidewalks
Playgrounds	\$35,000.00			Replace existing playground surfacing
Exterior Masonry	\$45,000.00			Misc Exterior Brick Repointing
Windows	\$1,317,600.00			Replace all windows
Ceilings	\$321,000.00			Replace all concealed spline ceilings
Interior Doors and Hardware	\$67,500.00			Replace Locksets with High Security/partial door replacement
Plumbing Fixtures	\$280,000.00			Replace Multi-Stall toilets (1 set), Classroom sinks and cabinets
Air Handling and Ventilation	\$1,180,000.00			Replace all Unit Ventilators, and Provide Mechanical fresh air ventilation to all student/staff occupied spaces
Temperature Controls	\$125,000.00			Replace existing temperature control system
Handicapped Assessibility	\$425,000.00			Provide ADA toilets - Faculty, Nurse, Drinking Fountains and access to upper rooms behind cafeteria etc.
Construction Cost Totals	\$3,946,100.00			
Note: Above costs are Construc Fees, CM, Legal Fees, Printing a	ction(hard costs) only and Construciton cost	r - 18% Soft cost contingencies t	s and Contingency s to cover unforseen o	should be added to cover the following - A/E fees, testing conditions which may arise throughout the project.

William Rall Elementary School

Description of Work	Priority A	Priority B	Priority C	Comments
Fuel Oil Tank	\$12,000.00			Replace cracked tank slab
Electrical Service	\$135,000.00			Replace existing electrical service
Sidewalks	\$85,000.00			Replace cracked sidewalks/Provide ADA access
Asphalt Pavement	\$351,300.00			Main parking lot and South side of building
Playgrounds	\$86,750.00			Replace existing playground surfacing
Foundation	\$5,000.00			Repair Foundation crack outside room 118
Exterior Masonry	\$40,000.00			Misc Exterior Brick Repointing
Chimney	\$8,000.00			Brick repointing
Roof Replacement	\$1,799,390.00			Replace entire roof - No longer under warranty
Ceilings	\$356,400.00			Replace all concealed spline ceilings/metal pan ceiling in kitchen
Interior Doors and Hardware	\$100,000.00			Replace Locksets with High Security/partial door replacement/Install panic Hardware on smoke doors to comply with BCNYS
Plumbing Fixtures	\$919,000.00			Replace Multi-Stall toilets, Classroom sinks and cabinets
Air Handling and Ventilation	\$3,300,000.00			Replace all Unit Ventilators, and Provide Mechanical fresh air ventilation to all student/staff occupied spaces convert system from steam to hot water
Fire Alarm System	\$125,000.00			Replace fire and smoke alarm system
Temperature Controls	\$125,000.00			Replace existing temperature control system
Handicapped Assessibility	\$125,000.00			Provide ADA toilets - Faculty, Nurse, Drinking Fountains
Construction Cost Totals	\$7,572,840.00			

Note: Above costs are Construction(hard costs) only - 18% Soft costs and Contingency should be added to cover the following - A/E fees, testing Fees, CM, Legal Fees, Printing and Construction cost contingencies to cover unforseen conditions which may arise throughout the project.

Description of Work	Priority A	Priority B	Priority C	Comments	
Electrical Service	\$175,000.00			Replace existing electrical service	
Sidewalks	\$35,000.00			Replace cracked sidewalks	
Exterior Masonry	\$10,000.00			Repoint FAI, Caulk Expansion joints	
Window Replacement	\$1,500,000.00			Replace all windows	
Roof Replacement	\$1,100,000.00			Replace entire roof - No longer under warranty	
Ceilings	\$527,000.00			Replace all concealed spline ceilings	
Interior Doors and Hardware	\$87,500.00			Replace Locksets with High Security/partial door replacement/Provide smoke zone exiting from GP roon	
Plumbing Fixtures	\$946,500.00			Replace Multi-Stall toilets, Classroom sinks and cabinet	
Air Handling and Ventilation	\$1,140,000.00			Replace all Unit Ventilators, and Provide Mechanical fresh air ventilation to all student/staff occupied space.	
Temperature Controls	\$125,000.00			Replace existing temperature control system	
Handicapped Assessibility	\$425,000.00			Provide ADA toilets - Faculty, Nurse, Drinking Fountains	
Construction Cost Totals	\$6,071,000.00				
Note: Above costs are Constructions and Construc	ction(hard costs) only and Construciton cost	- 18% Soft cos contingencies	ts and Contingency s to cover unforseen	should be added to cover the following - A/E fees, testing conditions which may arise throughout the project.	

Lindenhurst Middle School

Description of Work	Priority A	Priority B	Priority C	Comments
Asphalt Pavement	\$64,000.00			Overflow lot adj. to Tennis courts
Sidewalks	\$15,000.00			Provide ADA access from upper lot to tennis courts
Tennis Courts	\$480,000.00			Replace existing tennis courts
Exterior Masonry	\$225,000.00			Masonry Reconstruction and lintel replacement
Window Replacement	\$1,146,960.00			Partial window replacement and counter balance
				replacement - West side of 2 story wing and courtyard
				windows.
Interior Walls	\$75,000.00			Extensive plaster repair
Corridor Lockers	\$228,600.00			Replace remaining original lockers
Ceilings	\$144,000.00			Replace all concealed spline ceilings
Interior Doors and Hardware	\$150,000.00			Replace Locksets with High Security/partial door replacement/Provide panic hardware on smoke doors
Handicapped Ramp	\$5,000.00			provide hand rails on ramp to tech wing
Plumbing Fixtures	\$1,241,000.00			Replace Multi-Stall toilets, Classroom sinks and cabinets and locker room facilities
Boilers	\$345,000.00			Replace 1 boiler in main boiler room and re-use exsiting burner
Air Handling and Ventilation	\$4,700,000.00			Replace all Unit Ventilators, and Provide Mechanical fresh air ventilation to all student/staff occupied spaces - convert system from steam to hot water
Generator	\$500,000.00			replace 2 small generators with 1 whole building system
Handicapped Assessibility	TBD			Further discussion required regarding handicapped
				access to locker rooms
Construction Cost Totals	\$9,319,560.00			

,8,	Threing and constructed	on cost contingency	es to cover amorsee	ii condicions which m	y arise throughout the proje	LL.
				T		
-						

Lindenhurst High School

Description of Work	Priority A	Priority B	Priority C	Comments
Asphalt Pavement	\$197,790.00			Repave large asphalt area outside gym
Sidewalks	\$25,000.00			Replace cracked flags
Tennis Courts	\$540,000.00			Replace existing tennis courts
Exterior Masonry	\$20,000.00			Misc. masonry repairs
Window Replacement	\$47,000.00			Partial window replacement - pool area
Exterior steps	TBD			No ADA access to several stairs in vestibules - further
				discussion required
Interior Walls	\$22,000.00			repair masonry cracks at stage walls
Corridor Lockers	\$785,000.00			Replace remaining original lockers
Ceilings	\$1,973,975.00			Replace all concealed spline ceilings
Interior Doors and Hardware	\$150,000.00			Replace Locksets with High Security/partial door
				replacement/Gym doors - Priority 1
Elevator	\$110,000.00			
				Replace cab and upgrade controls and safety features
Plumbing Fixtures	TBD			
				Long Range Plan to upgrade remaining toilets/locker
				room facilities - further discussion required
Boilers	\$950,000.00			Replace 3 boiler in main boiler room and 1 in pool boiler
				room
Air Handling and Ventilation	\$3,488,000.00			Replace all Unit Ventilators, and Provide Mechanical
				fresh air ventilation to all student/staff occupied spaces/
				replace 2 RTU's
Handicapped Assessibility	\$1,875,000.00			ADA sinks in art, Science etc., ADA in Nurse's office,
				faculty toilets, place of refuge at exits, DF's
				-
Construction Cost Totals	\$10,183,765.00			
			NAMES OF THE PERSON OF THE PER	

Note: Above costs are Construction(hard costs) only - 18% Soft costs and Contingency should be added to cover the following - A/E fees, testing

Description of Work	Priority A	Priority B	Priority C	Comments
Sidewalks	\$21,000.00			Replace sidewalks along N. Putnam Ave.
Exterior Masonry	\$85,000.00			Misc. masonry repairs - S/P - lintels
xterior Doors	\$48,200.00			Replace metal panels above gym doors
Window Replacement	\$1,300,000.00			Building wide window replacement
Roof replacement	\$1,406,265.00			Replace entire roof - No warranty
nterior Doors and Hardware	\$85,000.00			Replace Locksets with High Security/partial door replacement
PA System	\$140,000.00			Replace existing PA and intercom system
Plumbing Fixtures	\$300,000.00			Renovate 2 pair of multi stall corridor toilets
Air Handling and Ventilation	TBD			Consider replacement of all Unit Ventilators
emperature Controls	\$75,000.00			Replace existing temperature controls system
Handicapped Assessibility	\$1,400,000.00			Construct new elevator for handicapped access to all floors
Construction Cost Totals	\$4,860,465.00			
				should be added to cover the following - A/E fees, testing conditions which may arise throughout the project.
	-			

Kellum School

Description of Work	Priority A	Priority B	Priority C	Comments
Sidewalks	\$20,000.00			Replace cracked flags
Exterior Masonry	\$45,000.00			Misc. masonry repairs
Chimney	\$7,500.00			Masonry repointing
Window Replacement	\$2,365,000.00			Building wide window replacement
Roof replacement	\$2,478,000.00			Replace entire roof - No warranty
Ceilings	\$89,000.00			Replace gymnasium ceiling
Interior Doors and Hardware	\$120,000.00			Replace Locksets with High Security/partial door
				replacement/install panic hardware on doors leading
				from places of public assembly/install cross corridor
				smoke doors outside GP room to create proper smoke
				zone exiting
PA System	\$215,000.00			Replace existing PA and intercom system
Plumbing Fixtures	TBD			Long Range Plan to upgrade toilets - further discussion
				required
Air Handling and Ventilation	\$2,600,000.00			Replace all Unit Ventilators, and Provide Mechanical
				fresh air ventilation to all student/staff occupied spaces
Temperature Controls	\$125,000.00			Replace existing temperature controls system
Handicapped Assessibility	\$425,000.00			ADA sinks, ADA in Nurse's office, faculty toilets, DF's etc
Construction Cost Totals	\$8,489,500.00			
				should be added to cover the following - A/E fees, testing
Fees, CM, Legal Fees, Printing	and Construciton cos	t contingencies	to cover unforseen	conditions which may arise throughout the project.
	T	ſ		
			1 = = = = =	