



1. Drill holes in horizontal frame for cable ties.




2. Manage cables horizontally by using cable ties.


Note: It's recommended that cables should be supported every 54".




3. Route cable(s) with attached data jack through hole in skin.



4. Find the corresponding jack holder per assembly instructions given with the “data tree”. Snap the jack holder in the modular data bezel.



5. Snap the data jack into the jack holder coming from the back side of the modular data bezel.



6. Snap data bezel into hole in skin.

