

Inductive sensor Bi1,5-H08K-AP6X-V1131





- stainless steel, 1.4301
- 3-wire DC, 10...30 VDC
- normally open, pnp output
- connector, M8 x 1

Wiring diagram



Туре	Bi1,5-H08K-AP6X-V1131
ldent-No.	1604330
Rated operating distance Sn	1.5 mm
Mounting condition	flush
Assured sensing range	≤ (0,81 x Sn) mm
Correction factors	$St37 = 1$, $V2A \sim 0.7$, $Ms \sim 0.4$, $Al \sim 0.3$
Temperature drift	≤ ± 10 %
Hysteresis	3 15 %
Repeatability	≤ 2 %
Ambient temperature	-25+ 70 °C
Operating voltage	10 30VDC
Residual ripple	≤ 10 % U _{ss}
DC rated operational current	≤ 150 mA
No-load current I ₀	≤ 15 mA
Residual current	≤ 0.1 mA
Rated insulation voltage	≤ 0.5 kV
Short-circuit protection	yes / cyclic
Voltage drop at I _e	≤ 1.8V
Wire breakage / Reverse polarity protection	yes / complete
Output function	3-wire, NO, pnp
Switching frequency	≤3kHz
Housing	smooth barrel, 8 mm
Dimensions	45 x 8 mm
Housing material	metal, AISI 304
Material active face	plastic, PA12-GF30
Connection	Connectors, M8 x 1
Vibration resistance	55 Hz (1 mm)
Shock resistance	30g (11 ms)
Degree of protection	IP67
Display switch state	LED yellow

Functional principle

Inductive sensors are designed for wearfree and non-contact detection of metal objects. For this purpose they use a highfrequency electro-magnetic AC field that interacts with the target. Conserning inductive sensors, this field is generated by an LC resonant circuit with a ferrite core coil.





Mounting instructions	minimum distances	_
Distance D	2 x B	
Distance W	3 x Sn	
Distance T	3 x B	
Distance S	1.5 x B	
Distance G	6 x Sn	
Diameter of the active area B	Ø 8 mm	

