

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193



Work Order # 32 [R&R ALTERNATOR]			Status COMPLETED			
Entity Name Battle Lumber Co.		Budget 0900 MAINTENANCE SHOP		Created 11/8/2018		
Priority Normal		Assigned Roger Mckenzie		Due 11/8/2018		
Work Type CORRECTIVE		Customer		Completed 11/8/2018		
Asset						
Asset ID 907193 [TAYLOR 0916]				Schedule		
Group Tree \0700 DRY KILN		Manufacturer TAYLOR				
Category FORKLIFTS		Model TE360				
Type FORKLIFT		Serial # S-H8-22550				
Logs						
Down Hours: 0.500000		Hours: 1055				
Services						
Service Code		Service Description			Estimated Hours	
MAINTENANCE						
[√]	INSTALL ALTERNATOR	INSTALL ALTERNATOR			1.00	
Parts						
Part #	Description	Location	Unit of Measure	Unit Cost	Quantity	Total
213-4011SW	REMAN ALTERNATOR	LUMBER WAREHOUSE [ ]	EACH	\$49.810	1.00	\$49.81

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193



Work Order # 164 [JUMP OFF]		Status COMPLETED
Entity Name Battle Lumber Co.	Budget 0700 DRY KILN	Created 11/27/2018
Priority Normal	Assigned Jeff Sherrod	Due 11/27/2018
Work Type CORRECTIVE	Customer	Completed 11/27/2018
Asset		
Asset ID 907193 [TAYLOR 0916]		Schedule
Group Tree \0700 DRY KILN	Manufacturer TAYLOR	
Category FORKLIFTS	Model TE360	
Type FORKLIFT	Serial # S-H8-22550	
Logs		
Down Hours: 0.500000	Hours: 1074	
Services		
Service Code	Service Description	Estimated Hours
STANDARD		
[√]	JUMP OFF JUMP OFF	0.25
Parts		

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193




<b>Work Order #</b> 458 [REPLACE STARTER, AND VALVE COVER GASKET]		<b>Status</b> COMPLETED
<b>Entity Name</b> Battle Lumber Co.	<b>Budget</b> 0700 DRY KILN	<b>Created</b> 12/17/2018
<b>Priority</b> Normal	<b>Assigned</b> Jeff Sherrod	<b>Due</b> 12/4/2018
<b>Work Type</b> CORRECTIVE	<b>Customer</b>	<b>Completed</b> 12/4/2018
<b>Asset</b>		
<b>Asset ID</b> 907193 [TAYLOR 0916]		<b>Schedule</b>
<b>Group Tree</b> \0700 DRY KILN	<b>Manufacturer</b> TAYLOR	
<b>Category</b> FORKLIFTS	<b>Model</b> TE360	
<b>Type</b> FORKLIFT	<b>Serial #</b> S-H8-22550	
<b>Logs</b>		
<b>Down Hours:</b> 1.500000		<b>Hours:</b> 1085
<b>Services</b>		
<b>Service Code</b>	<b>Service Description</b>	<b>Estimated Hours</b>
STANDARD		
[√]	START AND CHARGING SYST. CHECK START AND CHARGING SYSTEM	1.00
[√]	VALVE COVER GASKET VALVE COVER GASKET	1.00
<b>Parts</b>		

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193



<b>Work Order #</b> 5636 [START AND CHARGING SYSTEM]		<b>Status</b> COMPLETED				
<b>Entity Name</b> Battle Lumber Co.	<b>Budget</b> 0700 DRY KILN	<b>Created</b> 8/8/2019				
<b>Priority</b> Normal	<b>Assigned</b> Albert Lyn Barton	<b>Due</b>				
<b>Work Type</b> CORRECTIVE	<b>Customer</b>	<b>Completed</b> 8/8/2019				
<b>Asset</b>						
<b>Asset ID</b> 907193 [TAYLOR 0916]		<b>Schedule</b>				
<b>Group Tree</b> \0700 DRY KILN	<b>Manufacturer</b> TAYLOR					
<b>Category</b> FORKLIFTS	<b>Model</b> TE360					
<b>Type</b> FORKLIFT	<b>Serial #</b> S-H8-22550					
<b>Logs</b>						
<b>Down Hours:</b> 1		<b>Hours:</b> 1092				
<b>Services</b>						
<b>Service Code</b>	<b>Service Description</b>	<b>Estimated Hours</b>				
<b>MAINTENANCE</b>						
[ ]	INSTALL/ REPLACE BATTERY	INSTALL/ REPLACE BATTERY	1.00			
<b>Parts</b>						
<b>Part #</b>	<b>Description</b>	<b>Location</b>	<b>Unit of Measure</b>	<b>Unit Cost</b>	<b>Quantity</b>	<b>Total</b>
4D-XHD	INTERSTATE BATTERY	LUMBER WAREHOUSE [ ]	EACH	\$161.950	1.00	\$161.95
<b>Signatures</b>						
<b>Status</b>	<b>Note</b>	<b>Recorded By</b>		<b>Date</b>		
NEEDS REVIEW		Albert Lyn Barton		8/8/2019		
						

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193



Work Order # 6520 [Jump start ]		Status COMPLETED
Entity Name Battle Lumber Co.	Budget 0700 DRY KILN	Created 9/16/2019
Priority Normal	Assigned Roger Mckenzie	Due
Work Type CORRECTIVE	Customer	Completed 9/16/2019
Asset		
Asset ID 907193 [TAYLOR 0916]		Schedule
Group Tree \0700 DRY KILN	Manufacturer TAYLOR	
Category FORKLIFTS	Model TE360	
Type FORKLIFT	Serial # S-H8-22550	
Logs		
Down Hours: 0.250000		Hours: 1093
Services		
Service Code	Service Description	Estimated Hours
STANDARD		
[√]	JUMP OFF JUMP OFF	0.25
Parts		
Signatures		
Status	Note	Recorded By Date
NEEDS REVIEW		Roger Mckenzie 9/16/2019

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193



Work Order # 9071 [Won't start.]		Status COMPLETED				
Entity Name Battle Lumber Co.	Budget 0700 DRY KILN	Created 1/8/2020				
Priority Normal	Assigned James Rogers	Due				
Work Type CORRECTIVE	Customer	Completed 1/8/2020				
Asset						
Asset ID 907193 [TAYLOR 0916]		Schedule				
Group Tree \0700 DRY KILN	Manufacturer TAYLOR					
Category FORKLIFTS	Model TE360					
Type FORKLIFT	Serial # S-H8-22550					
Logs						
Down Hours: 0.750000		Hours: 1111				
Services						
Service Code	Service Description	Estimated Hours				
STANDARD						
[√]	START AND CHARGING CHECK START AND CHARGING SYSTEM SYST.	1.00				
Parts						
Part #	Description	Location	Unit of Measure	Unit Cost	Quantity	Total
I-4DXHD	Interstate battery	LUMBER WAREHOUSE [ ]	EACH	\$165.950	1.00	\$165.95
Signatures						
Status	Note	Recorded By		Date		
NEEDS REVIEW		James Rogers		1/8/2020		

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193



<b>Work Order # 13509 [Hydraulic leak ]</b>			<b>Status COMPLETED</b>			
<b>Entity Name</b> Battle Lumber Co.		<b>Budget</b> 0700 DRY KILN		<b>Created</b> 5/18/2020		
<b>Priority</b> Normal		<b>Assigned</b> Roger Mckenzie		<b>Due</b>		
<b>Work Type</b> CORRECTIVE		<b>Customer</b>		<b>Completed</b> 5/18/2020		
<b>Asset</b>						
<b>Asset ID</b> 907193 [TAYLOR 0916]				<b>Schedule</b>		
<b>Group Tree</b> \0700 DRY KILN		<b>Manufacturer</b> TAYLOR				
<b>Category</b> FORKLIFTS		<b>Model</b> TE360				
<b>Type</b> FORKLIFT		<b>Serial #</b> S-H8-22550				
<b>Logs</b>						
<b>Down Hours:</b> 2		<b>Hours:</b> 1112				
<b>Services</b>						
<b>Service Code</b>		<b>Service Description</b>			<b>Estimated Hours</b>	
<b>MAINTENANCE</b>						
[√]		HYDRAULIC LEAK HYDRAULIC LEAK			1.00	
<b>Parts</b>						
<b>Part #</b>	<b>Description</b>	<b>Location</b>	<b>Unit of Measure</b>	<b>Unit Cost</b>	<b>Quantity</b>	<b>Total</b>
T2090-0808	0808 NPT MALE FITTING	LUMBER WAREHOUSE [ ]	EACH	\$3.610	8.00	\$28.88
T28D	EXCEEDS SAE 1/2' 100R2AT DIEHARD COVER	LUMBER WAREHOUSE [ ]	FEET	\$2.450	6.00	\$14.70
DELO 15W40 GAL.	DELO 15W40 GALLONS	LUMBER WAREHOUSE [ ]	GALLONS	\$13.000	1.00	\$13.00
SUS65G	SUPER S GREEN ANTIFREEZE	LUMBER WAREHOUSE [ ]	EACH	\$8.292	1.00	\$8.29
<b>Signatures</b>						
<b>Status</b>	<b>Note</b>	<b>Recorded By</b>		<b>Date</b>		
NEEDS REVIEW		Roger Mckenzie		5/18/2020		

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193



Work Order # 13906 [Hydraulic leak ]			Status COMPLETED			
Entity Name Battle Lumber Co.		Budget 0700 DRY KILN		Created 5/29/2020		
Priority Normal		Assigned Albert Lyn Barton		Due		
Work Type CORRECTIVE		Customer		Completed 6/10/2020		
Asset						
Asset ID 907193 [TAYLOR 0916]				Schedule		
Group Tree \0700 DRY KILN		Manufacturer TAYLOR				
Category FORKLIFTS		Model TE360				
Type FORKLIFT		Serial # S-H8-22550				
Logs						
Down Hours: 2		Hours: 1114				
Services						
Service Code		Service Description			Estimated Hours	
MAINTENANCE						
[√]		HYDRAULIC LEAK		HYDRAULIC LEAK		1.00
Parts						
Part #	Description	Location	Unit of Measure	Unit Cost	Quantity	Total
5406-C-06	NPT CAP	LUMBER WAREHOUSE [ ]	EACH	\$1.100	2.00	\$2.20
5406-P-06	PIPE PLUG 3/8	LUMBER WAREHOUSE [ ]	EACH	\$0.430	2.00	\$0.86
5406-C-08	NPT CAP	LUMBER WAREHOUSE [ ]	EACH	\$1.420	2.00	\$2.84
19-1045	MASTER DISCONNECT SWITCH	LUMBER WAREHOUSE [ ]	EACH	\$38.050	1.00	\$38.05
Signatures						
Status	Note	Recorded By		Date		
NEEDS REVIEW		Albert Lyn Barton		6/10/2020		

6/9/2021



# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193



<b>Work Order #</b> 16887 [Jump start ]		<b>Status</b> COMPLETED	
<b>Entity Name</b> Battle Lumber Co.	<b>Budget</b> 0700 DRY KILN	<b>Created</b> 8/21/2020	
<b>Priority</b> Normal	<b>Assigned</b> Roger Mckenzie	<b>Due</b>	
<b>Work Type</b> CORRECTIVE	<b>Customer</b>	<b>Completed</b> 8/21/2020	
<b>Asset</b>			
<b>Asset ID</b> 907193 [TAYLOR 0916]		<b>Schedule</b>	
<b>Group Tree</b> \0700 DRY KILN	<b>Manufacturer</b> TAYLOR		
<b>Category</b> FORKLIFTS	<b>Model</b> TE360		
<b>Type</b> FORKLIFT	<b>Serial #</b> S-H8-22550		
<b>Logs</b>			
<b>Down Hours:</b> 0.250000		<b>Hours:</b> 1118	
<b>Services</b>			
<b>Service Code</b>	<b>Service Description</b>	<b>Estimated Hours</b>	
<b>STANDARD</b>			
[√]	JUMP OFF	JUMP OFF	0.25
<b>Parts</b>			
<b>Signatures</b>			
<b>Status</b>	<b>Note</b>	<b>Recorded By</b>	<b>Date</b>
NEEDS REVIEW		Roger Mckenzie	8/21/2020

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193



Work Order # 18698 [Check battery ]			Status COMPLETED		
Entity Name Battle Lumber Co.		Budget 0700 DRY KILN		Created 10/15/2020	
Priority Normal		Assigned James Rogers		Due	
Work Type CORRECTIVE		Customer		Completed 10/15/2020	
Asset					
Asset ID 907193 [TAYLOR 0916]				Schedule	
Group Tree \0700 DRY KILN		Manufacturer TAYLOR			
Category FORKLIFTS		Model TE360			
Type FORKLIFT		Serial # S-H8-22550			
Logs					
Down Hours: 0.500000		Hours: 1123			
Services					
Service Code		Service Description			Estimated Hours
STANDARD					
[√]	START AND CHARGING SYST.	CHECK START AND CHARGING SYSTEM			1.00
Parts					
Part #	Description	Location	Unit of Measure	Unit Cost	Quantity Total
I-4DXHD	Interstate battery	LUMBER WAREHOUSE [ ]	EACH	\$165.950	1.00 \$165.95
Signatures					
Status	Note	Recorded By		Date	
NEEDS REVIEW		James Rogers		10/15/2020	
Jimmy					

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

907193



<b>Work Order # 26957 [Remove mast]</b>			<b>Status COMPLETED</b>			
<b>Entity Name</b> Battle Lumber Co.		<b>Budget</b> 0700 DRY KILN		<b>Created</b> 5/18/2021		
<b>Priority</b> Normal		<b>Assigned</b> James Rogers		<b>Due</b>		
<b>Work Type</b> CORRECTIVE		<b>Customer</b>		<b>Completed</b> 5/25/2021		
<b>Asset</b>						
<b>Asset ID</b> 907193 [TAYLOR 0916]				<b>Schedule</b>		
<b>Group Tree</b> \0700 DRY KILN		<b>Manufacturer</b> TAYLOR				
<b>Category</b> FORKLIFTS		<b>Model</b> TE360				
<b>Type</b> FORKLIFT		<b>Serial #</b> S-H8-22550				
<b>Logs</b>						
<b>Down Hours:</b> 4		<b>Hours:</b> 1159				
<b>Services</b>						
<b>Service Code</b>		<b>Service Description</b>			<b>Estimated Hours</b>	
<b>MAINTENANCE</b>						
[√]	CHECK ALL FLUID LEVELS	CHECK ALL FLUID LEVELS			0.25	
[√]	CHECK OVER	CHECK OVER			1.00	
[√]	REMOVE MAST	REMOVE MAST FROM FORKLIFT			1.00	
<b>Parts</b>						
<b>Part #</b>	<b>Description</b>	<b>Location</b>	<b>Unit of Measure</b>	<b>Unit Cost</b>	<b>Quantity</b>	<b>Total</b>
2408-10	10 MJ PLUG	LUMBER WAREHOUSE [ ]	EACH	\$0.990	3.00	\$2.97
0304-10	10 JIC LONG TUBE NUT	LUMBER WAREHOUSE [ ]	EACH	\$1.770	3.00	\$5.31
5406-C-08	NPT CAP	LUMBER WAREHOUSE [ ]	EACH	\$1.620	6.00	\$9.72
5406-P-08	PIPE PLUG 1/2	LUMBER WAREHOUSE [ ]	EACH	\$0.880	6.00	\$5.28
<b>Signatures</b>						
<b>Status</b>	<b>Note</b>	<b>Recorded By</b>		<b>Date</b>		
NEEDS REVIEW		James Rogers		5/25/2021		

# Work Order

Rainey, Troy: 6/9/2021 6:46:31 AM

A handwritten signature in black ink, appearing to read "Jimmy", is located in the top left corner of the page. The signature is written in a cursive style with a large initial "J".