

## HyDraw CAD® 2022 Hotfix 03 IT

Applicability: HyDraw CAD 2022 IT with Hotfix 02 IT installed

### Issues Resolved:

1. Unhandled exception error appearing when using the Insert Title Block command to open the same title block already present within the drawing.
2. Speed degradation appears when switching between Model and Paper space.
3. Speed degradation is present when using the Delete key on a symbol.
4. A lag is present when assigning Model Data to an External Port.
5. In special cases, flipping a symbol will result in all grip points disappearing for a symbol.
6. Multiple functions assigned to a solenoid are appearing as single-line text within the drawing.
7. Unhandled exception error appearing when searching for a part number within the database and receiving no results.
8. The Edit Title Block command does not recognize title blocks outside of the default HyDraw title blocks.
9. The Edit Title Block command does not recognize a title block already inserted when starting from a dwt file.

Date: February 17, 2023