



HyDraw[®] Library Manager 2026

Service Pack 1

Bug Fixes

Bugs Fixed



Component Import Not Linking in Symbol View:

1

When importing component data in Symbol View, the application failed to correctly link the imported data with the associated model.



Component Type Not Auto Populated During Excel Import:

2

When updating existing models using the Import Model Data from Excel feature in HLM 2026, the Component Type field was not automatically populated, even though the model codes already existed in the HLM library with a defined Component Type.



"Move Folder" Message Appears in Symbol View:

3

Rapidly clicking a subfolder in Symbol View triggered an unintended "Move Folder" message.



Column Resizing Issue in HyDraw Library Manager:

4

In the HyDraw Library Manager, column widths became fixed after selecting a Component Type. When the HLM window was not maximized, users were unable to resize columns, preventing proper viewing of model data.

Bugs Fixed



Blank Row Inserted in Model Data View:

5

A blank row was inserted when adding a new model code in Model Data View.



Update Symbol Library - Missing Symbols in Update Results:

6

Some symbols were missing from the Update Symbol Library results due to date inconsistencies.



Update Symbol Library - "Exclude Symbols I Modified" checkbox does not exclude symbols when running Replace All:

7

In the Update Symbol Library feature in HLM, the Exclude Symbols I Modified option did not function correctly. Modified symbols were still replaced when executing the Replace All Symbols operation.



Update Symbol Library - Component Type Mapping Dialog Appears Behind Other Windows:

8

During the Update Library process, if the user switches to another application and then returns to HLM, the Assign Component Type dialog may appear behind other windows. This gives the impression that the process is still running, while it is waiting for user input.

Bugs Fixed



Part Number Search Fails with Hyphenated Numeric Values:

9

Part Number search does not work correctly when the search value contains a hyphen followed by numbers.



SQL Login Failure with Passwords Longer Than 15 Characters:

10

In HLM 2026, login to the SQL library fails when using a password longer than 15 characters. Passwords with 15 or fewer characters work correctly.



Update Symbol Library - Symbols not updated correctly:

11

Some symbols were not updated correctly during the Update Symbol Library process.



Missing Buttons in "Link Existing Model" Dialog at 175% Display Scaling:

12

At 175% display scaling, the Add New and OK buttons are not visible in the Link Existing Model dialog.

Acronyms:

- * HLM - HyDraw Library Manager
- ** HLE - HyDraw Library Explorer
- *** HPM - Hydraw Property Manager