



HyDraw[®] CAD 2026

Service Pack 1

Bug Fixes

Bugs Fixed



Duplicate Net Names Generated:

Duplicate net names are generated when a network connection line is broken by inserting a new symbol.

1



Master Symbol Image Quality:

Editing and saving a master symbol reduces the original image resolution or size.

2



Align Symbol Ports Crash:

HyDraw CAD crashes when using the Align Symbol Ports function.

3



Component Sorting Order:

Components are not displayed in numerical order in System Tab of HyDraw property manager.

4



MDTools Export Hidden Ports:

Hidden port names are not exported to MDTools as expected.

5



MDTools Export Validation:

The system allows export even when a symbol does not contain a port name.

6



SQL Password Length Issue:

SQL database login fails in HyDraw CAD 2026 when the password exceeds 15 characters.

7



Incorrect ZIP file naming:

HyDraw CAD 2026 Import/Export settings ZIP file uses the 2025 naming convention.

8

Bugs Fixed



Property Manager Hover Exception:
An unhandled exception occurs when hovering while Property Manager is set to auto-hide.

9



MTEXT Disappearing After TRIM:
MTEXT Disappearing from Drawing After Using TRIM Command.

10



Item ID Exception with Drawing:
Inconsistent Item ID behavior and an unhandled exception occurred with a specific drawing.

11



Hidden Property Values:
When using an English Library with HyDraw CAD Italian, Property values become hidden when a prefix is added to the hose connector display format.

12



Assembly ID Disappears:
Assembly ID disappears from the envelope when its Item ID is changed.

13



Balloon Color Change Issue:
Changing color from BY LAYER to another color also changes the balloon color.

14



Overlapping Item IDs:
Copying a component with multiple accessories results in overlapping Item IDs.

15



Balloon Detaches After Replace:
Item ID and its balloon become detached after replacing a symbol.

16

Bugs Fixed



Multiple Window Launch Issue:

HyDraw CAD opens multiple windows when HLE and HPM are docked with auto-hide enabled and the command line is docked.

17



Small Balloons After Copy:

Balloons of copied symbols appear smaller than expected.

18



Multiple Windows on Startup:

Multiple windows open when launching HyDraw CAD due to HLE and HPM auto-hide settings.

19



Item ID Not Cleared when Assembly ID also exists:

Removing Item ID from HyDraw Property Manager does not clear the Item ID on the drawing when an Assembly ID also exists.

20

Acronyms:

- * HLM - HyDraw Library Manager
- ** HLE - HyDraw Library Explorer
- *** HPM - HyDraw Property Manager