

MDTools® 785 Hotfix 03

Applicability: MDTools 785 with SP1 and Hotfix 02

Issues Resolved:

1. Through holes were reporting an inapplicable wall thickness error with the face they go through.
2. Show engraving in drawing was failing for assembly drawings.

Date: Dec 28, 2022