

MDTools® 975 Hotfix 06

Applicability: MDTools 975 with Service Pack 3

Issue Resolved:

1. Drill tip in the model was incorrectly appearing flat if the Step above had a difference in diameter of .0002 or less.
2. Stretch Drill was displaying a blank depth value when a fraction was used for drill diameter.
3. Reverted changes from Service Pack 3 from using Custom Scales for View Scale to using Sheet Scale for View Scale.

Date: May 11, 2023