

MDTools® 980 Hotfix 02

Applicability: MDTools 980 SP1.1 and with or without Hotfix 01 installed

Issues Resolved:

1. MDTools was creating a duplicate cavity on the Stretch Block for a specific scenario.
2. Speed Improvement for various commands like Change Face, Copy Cavity, Copy Multiple and Swap Cavity.

Date: Feb 08, 2024