

MDTools® 980 Hotfix 04

Applicability: MDTools 980 with Service Pack 2.

Issues Resolved:

1. MDTools was swapping the nets of a cartridge valve upon an orifice being inserted using merge with parent cavity option through the HyDraw Schematic interface.

Date: Apr 03, 2025