

MDTools® 985 Hotfix 01

Applicability: MDTools 985 Installed.

Issues Resolved:

1. MDTools threw an error while creating the Machining Chart “By Face” when the "Row Separator" option was set to "NO".
2. MDTools was wrongly creating a fillet on the edge with the working area of “Counterbore” O-rings.
3. MDTools failed to open a new part when using the Import MBXML command with specific part files.
4. The Align Engraving command did not function when the engraving overlapped with a cavity feature.
5. Millimeter O-ring machining sequence information was displayed under Inch O-ring machining details.

Date: Jul 02, 2025