

## MDTools 985 Hotfix 04

**Applicability:** MDTools 985 with Service Pack 2 Installed.

**Issues Resolved:**

1. MDTools Conformance to Schematic check was unable to detect incorrect net names and port types for flanges.
2. Cavities without Step12 incorrectly updated the depth of the bottom step when stretching the block.

Date: Apr 29, 2026