

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {3002}

LOCATION ON US 41 1.3 MI S OF SR 18
MP# 199.9

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
02-19-10	10:am	Reset WIM	Richard Martin	317-695-4773	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {3002}

LOCATION ON US 41 1.3 MI S OF SR 18
MP# 199.9

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
04-20-10	2:10pm	changed the power switch on WIM	Donn Klepinger	317-591-5264	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3002}

LOCATION ON US 41 1.3 MI S OF SR 18
 MP# 199.9

TYPE EQUIPMENT PERMANENT WIM
 MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
04-08-10	11:45am	Bypassed UPS	Donn Klepinger	317-591-5264	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {3002}

LOCATION ON US 41 1.3 MI S OF SR 18
MP# 199.9

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
03-26-10	01:25 pm	Replaced UPS.	Donn Klepinger	317-591-5264	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {3002}

LOCATION ON US 41 1.3 MI S OF SR 18
MP# 199.9

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
03-19-10	11:00 am	Removed and bypassed UPS	Donn Klepinger	317-591-5264	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3002}

LOCATION ON US 41 1.3 MI S OF SR 18
MP# 199.9

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
05-21-10	11:45 am	Reported bad phone line to Phone Company	Donn Klepinger	317-591-5264	N/A

revised November 11, 1999