

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6300

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {3031 / 4042}

LOCATION ON SR 62 2.6 MI E OF SR 69
MP# 12.5

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
01-28-09	6:17pm	Site inspection. All loops need respliced. P4 needs replaced	Jeff Wourms	317-694-4224	

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6300

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {3031 / 4042}

LOCATION ON SR 62 2.6 MI E OF SR 69
MP# 12.5

TYPE EQUIPMENT PERMANENT WIM
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
04-01-09	3:30pm	Replace P4. Respliced all 8 loops. Replaced temprature sensor.	Jeff Wourms	317-694-4224	

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6300

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3031 / 4042}

LOCATION ON SR 62 2.6 MI E OF SR 69
MP# 12.5

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
04-07-09	3:10pm	Reported bad phone line to phone company.	Richard Martin	317-695-4773	

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6300

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3031 / 4042}

LOCATION ON SR 62 2.6 MI E OF SR 69
MP# 12.5

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
04-15-09	9:54am	Reset WIM and modem	Richard Martin	317-695-4773	

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6300

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {3031 / 4042}

LOCATION ON SR 62 2.6 MI E OF SR 69
MP# 12.5

TYPE EQUIPMENT PERMANENT WIM
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
04-30-09	1:47pm	WIM still not working. Will need new WIM.	Larry Torrance	317-591-5262	

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6300

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3031 / 4042}

LOCATION ON SR 62 2.6 MI E OF SR 69
MP# 12.5

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
05-05-09	1:45pm	Replace WIM recorder	Larry Torrance	317-591-5262	

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6300

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {3031 / 4042}

LOCATION ON SR 62 2.6 MI E OF SR 69
MP# 12.5

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
05-07-09	3:00pm	Replace modem and modem power supply	Larry Torrance	317-591-5262	

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6300

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3031 / 4042}

LOCATION ON SR 62 2.6 MI E OF SR 69
MP# 12.5

TYPE EQUIPMENT PERMANENT WIM
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
12-09-09	2:00pm	Cabinet replaced and re wired	Larry Torrance	317-591-5262	

revised November 11, 1999