

STATION 4500

LOCATION	ON SR 2 2.84 MI W OF US 20
MP#	65.2

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

[illegible]

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 4500

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {5528 / 5538}

LOCATION ON SR 2 2.84 MI W OF US 20
MP# 65.2

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
08-24-09	04:40pm	WIM shut down. Reset WIM and modem	Larry Torrance	317-591-5265	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 4500

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {5528 / 5538}

LOCATION ON SR 2 2.84 MI W OF US 20
MP# 65.2

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
09-29-09	02:30pm	Reset modem timer.	Larry Torrance	317-591-5265	N/A

revised November 11, 1999