

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6100

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {6012}

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
 MP# 27.9

TYPE EQUIPMENT  
 MODEL #

PERMANENT WIM  
 IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
01-29-09	1040am	Site inspection. All loops need respliced. P1, P2, P4, P5 need replaced	Jeff Wourms	317-694-4224	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6100

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {6012}

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
MP# 27.9

TYPE EQUIPMENT PERMANENT WIM  
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
04-14-09	4:15pm	Replaced piezos 1,2,4,5. Respliced all loops	Jeff Wourms	317-694-4224	N/A

revised November 11, 1999

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6100

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {6012}

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
MP# 27.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
04-15-09	10:40am	Plugged in phone cord from phone jack to modem	Richard Martin	317-695-4773	N/A

revised November 11, 1999

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6100

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{6012}

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
MP# 27.9

TYPE EQUIPMENT PERMANENT WIM  
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
05-08-09	11:45am	Reprted bad phone line to phone company.	Larry Torrance	317-591-5265	N/A

revised November 11, 1999

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6100

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{6012}

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
MP# 27.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
05-12-09	12:30pm	Calibrated WIM	Jeff Wourms	317-694-4224	N/A

revised November 11, 1999

## LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

PERMANENT WIM  
IRD 1067

[illegible]

revised November 11, 1999

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6100

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{      }
	*STATE CODE	{18}
	*SHRP SECTION ID	{6012}

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
MP# 27.9

TYPE EQUIPMENT PERMANENT WIM  
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
08-12-09	10:15am	Reset UPS	Larry Torrance	317-591-5262	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6100

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{6012}

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
MP# 27.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
08-26-09	02:10pm	Reset UPS	Donn Klepinger	317-591-5265	N/A

revised November 11, 1999



# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6100

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{6012}

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
MP# 27.9

TYPE EQUIPMENT PERMANENT WIM  
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
09-10-09	1:20pm	Removed UPS	Richard Martin	317-695-4773	N/A

revised November 11, 1999

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6100

<p>SHEET 15 LTPP TRAFFIC DATA</p> <p>LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM</p>	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{6012}

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
MP# 27.9

TYPE EQUIPMENT PERMANENT WIM  
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
10-29-09	2:45pm	Reset UPS	Larry Torrance	317-591-5265	N/A

revised November 11, 1999

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 6100

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{6012}

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
MP# 27.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
12-03-09	2:20pm	Power restored	Larry Torrance	317-591-5265	N/A

revised November 11, 1999

## STATION 6100

LOCATION ON I 64 1.5 MI W OF I 164 / SR 57  
MP# 27.9

TYPE EQUIPMENT	PERMANENT WIM
MODEL #	IRD 1067.

[illegible]

revised November 11, 1999