

STATION 3600

LOCATION ON I 70 4.3 MI E OF SR 9
MP# 108.0

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

[illegible]

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 3600

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{A900}

LOCATION ON I 70 4.3 MI E OF SR 9
MP# 108.0

TYPE EQUIPMENT PERMANENT WIM
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
3-08-10	12:45pm	Reset WIM and modem	Larry Torrance	317-591-5265	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 3600

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{A900}

LOCATION ON I 70 4.3 MI E OF SR 9
MP# 108.0

TYPE EQUIPMENT PERMANENT WIM
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
2-19-10	12:15pm	Reported bad phone line	Donn Klepinger	317-591-5264	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 3600

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{A900}

LOCATION ON I 70 4.3 MI E OF SR 9
MP# 108.0

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
3-09-10	02:30pm	Reset WIM and modem	Larry Torrance	317-591-5265	N/A

revised November 11, 1999