

SHEET 13 12 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [304]
	STATE CODE [26]
	SHRP SECTION ID [1012]

HIGHWAY RT. NO. (THIS SESSION) US 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME C261012.IP3 DISK/TAPE ID _____

BEGINNING DATE 7-26-93 BEGINNING TIME 13:00

ENDING DATE 7-31-93 ENDING TIME 23:55

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET <u>13</u> <u>12</u> LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>304</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>012</u>]

HIGHWAY RT. NO. (THIS SESSION) 45 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME C261012.J13 DISK/TAPE ID _____

BEGINNING DATE 8-1-93 BEGINNING TIME 00:00

ENDING DATE 8-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET <u>1312</u> LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>309</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>1012</u>]

HIGHWAY RT. NO. (THIS SESSION) 45 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME C261012-K13 DISK/TAPE ID _____

BEGINNING DATE 9-1-93 BEGINNING TIME 00:00

ENDING DATE 9-30-91 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13 <u>12</u> LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>304</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>1012</u>]

HIGHWAY RT. NO. (THIS SESSION) US 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME C261012.L13 DISKTAPE ID _____

BEGINNING DATE 10-1-93 BEGINNING TIME 00:00

ENDING DATE 10-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FHWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 1812
LTPP TRAFFIC DATA

VEHICLE WEIGHT DATA
TRANSMITTAL FORM

STATE ASSIGNED ID [304]

STATE CODE [26]

SHRP SECTION ID [1012]

HIGHWAY RT. NO. (THIS SESSION) US 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME C261012.M13 DISK/TAPE ID _____

BEGINNING DATE 10-1-93 BEGINNING TIME 00:00

ENDING DATE 11-30-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FHWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER James Kramer PHONE # 517-322-1736

DATE PREPARED _____

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>304</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>1012</u>]

HIGHWAY RT. NO. (THIS SESSION) US 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME W261012.IP3 DISK/TAPE ID _____

BEGINNING DATE 7-26-93 BEGINNING TIME 13:00

ENDING DATE 7-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [☒] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM ☒ OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>304</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>1012</u>]

HIGHWAY RT. NO. (THIS SESSION) 45 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME W261012.J13 DISK/TAPE ID _____

BEGINNING DATE 8-1-93 BEGINNING TIME 00:00

ENDING DATE 8-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [☒] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

<p align="center">SHEET 13</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">VEHICLE WEIGHT DATA TRANSMITTAL FORM</p>	STATE ASSIGNED ID [<u>309</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>1013</u>]

HIGHWAY RT. NO. (THIS SESSION) US 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME W261012.K13 DISK/TAPE ID _____

BEGINNING DATE 9-1-93 BEGINNING TIME 00:00

ENDING DATE 9-30-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [☒] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13
LTPP TRAFFIC DATA
VEHICLE WEIGHT DATA
TRANSMITTAL FORM

STATE ASSIGNED ID [304]
STATE CODE [26]
SHRP SECTION ID [1012]

HIGHWAY RT. NO. (THIS SESSION) US 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME 0261012.L13 DISK/TAPE ID _____

BEGINNING DATE 10-1-93 BEGINNING TIME 00:00

ENDING DATE 10-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FHWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER James Kramer PHONE # 517-322-1736
DATE PREPARED _____

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>304</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>1012</u>]

HIGHWAY RT. NO. (THIS SESSION) US 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME 0261012.M13 DISK/TAPE ID _____

BEGINNING DATE 11-1-93 BEGINNING TIME 00:00

ENDING DATE 11-30-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [☒] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FHWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [304]
	STATE CODE [26]
	SHRP SECTION ID [1012]

HIGHWAY RT. NO. (THIS SESSION) US 131

MILEPOST NO. OR LOCATION (THIS SESSION) Big Rapids

FILENAME W261012.N13 DISKTAPE ID _____

BEGINNING DATE 12-1-93 BEGINNING TIME 00:00

ENDING DATE 12-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FHWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	