

| | | | | | |
|---------|--------|-------|---------|-------|-------|
| C271016 | 1/1/93 | 00:00 | 7/31/93 | 24:00 | Minn2 |
| W271016 | 1/1/93 | 00:00 | 7/31/93 | 24:00 | Minn2 |
| C274040 | 1/1/93 | 00:00 | 7/31/93 | 24:00 | Minn2 |
| W274040 | 1/1/93 | 00:00 | 7/31/93 | 24:00 | Minn2 |
| C271087 | 1/1/93 | 00:00 | 7/31/93 | 24:00 | Minn2 |
| W271087 | 1/1/93 | 00:00 | 7/31/93 | 24:00 | Minn2 |
| C274054 | 1/1/93 | 00:00 | 7/31/93 | 24:00 | Minn2 |
| W274054 | 1/1/93 | 00:00 | 7/31/93 | 24:00 | Minn2 |

NAME OF PREPARER: Vicky Sarner
DATE PREPARED: December 16, 1993

PHONE NO.: 612-296-8526

| | | | | | |
|---------|--------|-------|----------|-------|-------|
| C271016 | 8/1/93 | 00:00 | 12/31/93 | 24:00 | Minn2 |
| W271016 | 8/1/93 | 00:00 | 12/31/93 | 24:00 | Minn2 |
| C274040 | 8/1/93 | 00:00 | 12/31/93 | 24:00 | Minn2 |
| W274040 | 8/1/93 | 00:00 | 12/31/93 | 24:00 | Minn2 |
| C271087 | 9/1/93 | 00:00 | 12/31/93 | 24:00 | Minn2 |
| W271087 | 9/1/93 | 00:00 | 12/31/93 | 24:00 | Minn2 |
| C274054 | 9/1/93 | 00:00 | 12/31/93 | 24:00 | Minn2 |
| W274054 | 9/1/93 | 00:00 | 12/31/93 | 24:00 | Minn2 |

NAME OF PREPARER: Vicky Sarner
DATE PREPARED: March 28, 1994

PHONE NO.: 612-296-8526

SHEET 14

**LOG OF CHANGES AT GPS TEST
LOCATIONS WITH PERM. AVC OR WIM**

*STATE ASSIGNED ID [_1022_]

*STATE CODE [27]

*SHRP SECTION ID [_1087 _]

LOCATION TH 13 Eagan, MN TYPE EQUIP. Bending Plate

MP # 101.33 MODEL # IRD

[illegible]

SHEET 14
LTPP TRAFFIC DATA

LOG OF CHANGES AT GPS TEST
LOCATIONS WITH PERM. AVC OR WIM

*STATE ASSIGNED ID [1002]

*STATE CODE [27]

*SHRP SECTION ID [1087]

LOCATION TH-13, EAGAN, MN TYPE EQUIP. Bending Plate

MP # 101.33 MODEL # TRD

| DATE OF CHANGE | TIME OF CHANGE | DESCRIPTION OF CHANGE | PERSON MAKING CHANGE | PHONE # | NEW EQUIP. SERIAL # |
|----------------|----------------|--|----------------------|---------|---------------------|
| 9/20/93 | | Lane 1, Cell 1 not working. | M. Novak | | |
| 9/29/93 | | Upgraded site software to 7.3.2. | V. Sarnier | | |
| 10/20/93 | | Lane 2 & 4, Cell #4 #7 not working. | | | |
| 11/8/93 | | Cell 4 working. | | | |
| 11/24/93 | | Cell #7 working. Cell #8 not working. | | | |
| 11/30/93 | | Upgraded site software to 7.3.3. | | | |
| 11/28/93 | | Cell #7 not working. | | | |
| | | | | | |
| | | | | | |

LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM

*SHRP SECTION ID [1687]

| | | | |
|----------|-----------------|-------------|---------------|
| LOCATION | TH 13 Eagan, MN | TYPE EQUIP. | Bending Plate |
| MP # | 101.33 | MODEL # | TRD |

[illegible]