

Sheet 13  
Traffic Data Files  
Transmittal Form

State: Minnesota  
State Code: 27

FILE NAME	START DATE	START TIME	END DATE	END TIME	CLASS SCHEME
C271029	1/1/93	00:00	7/31/93	24:00	Minn2
W271029	1/1/93	00:00	7/31/93	24:00	Minn2
C279075	1/1/93	00:00	7/31/93	24:00	Minn2
W279075	1/1/93	00:00	7/31/93	24:00	Minn2
C271019	1/1/93	00:00	7/31/93	24:00	Minn2
W271019	1/1/93	00:00	7/31/93	24:00	Minn2
C273003	1/1/93	00:00	7/31/93	24:00	Minn2
W273003	1/1/93	00:00	7/31/93	24:00	Minn2
C271085	1/1/93	00:00	7/31/93	24:00	Minn2
W271085	1/1/93	00:00	7/31/93	24:00	Minn2
C271028	1/1/93	00:00	7/31/93	24:00	Minn2
W271028	1/1/93	00:00	7/31/93	24:00	Minn2
C274055	1/1/93	00:00	7/31/93	24:00	Minn2
W274055	1/1/93	00:00	7/31/93	24:00	Minn2
C271023	1/1/93	00:00	7/31/93	24:00	Minn2
W271023	1/1/93	00:00	7/31/93	24:00	Minn2
C276251	1/1/93	00:00	7/31/93	24:00	Minn2
W276251	1/1/93	00:00	7/31/93	24:00	Minn2
C273013	1/1/93	00:00	7/31/93	24:00	Minn2
W273013	1/1/93	00:00	7/31/93	24:00	Minn2
C274033	1/1/93	00:00	7/31/93	24:00	Minn2
W274033	1/1/93	00:00	7/31/93	24:00	Minn2
C274037	1/1/93	00:00	7/31/93	24:00	Minn2
W274037	1/1/93	00:00	7/31/93	24:00	Minn2
C274050	1/1/93	00:00	7/31/93	24:00	Minn2
W274050	1/1/93	00:00	7/31/93	24:00	Minn2

Sheet 13  
Traffic Data Files  
Transmittal Form

State: Minnesota  
State Code: 27

FILE NAME	START DATE	START TIME	END DATE	END TIME	CLASS SCHEME
C271029	8/1/93	00:00	12/31/93	24:00	Minn2
W271029	8/1/93	00:00	12/31/93	24:00	Minn2
C279075	8/1/93	00:00	12/31/93	24:00	Minn2
W279075	8/1/93	00:00	12/31/93	24:00	Minn2
C271019	9/1/93	00:00	12/31/93	24:00	Minn2
W271019	9/1/93	00:00	12/31/93	24:00	Minn2
C273003	8/1/93	00:00	12/31/93	24:00	Minn2
W273003	8/1/93	00:00	12/31/93	24:00	Minn2
C271085	9/1/93	00:00	12/31/93	24:00	Minn2
W271085	9/1/93	00:00	12/31/93	24:00	Minn2
C271028	8/1/93	00:00	12/31/93	24:00	Minn2
W271028	8/1/93	00:00	12/31/93	24:00	Minn2
C274055	8/1/93	00:00	12/31/93	24:00	Minn2
W274055	8/1/93	00:00	12/31/93	24:00	Minn2
C271023	8/11/93	00:00	12/31/93	24:00	Minn2
W271023	8/11/93	00:00	12/31/93	24:00	Minn2
C276251	8/11/93	00:00	12/31/93	24:00	Minn2
W276251	8/11/93	00:00	12/31/93	24:00	Minn2
C273013	8/1/93	00:00	12/31/93	24:00	Minn2
W273013	8/1/93	00:00	12/31/93	24:00	Minn2
C274033	8/1/93	00:00	12/31/93	24:00	Minn2
W274033	8/1/93	00:00	12/31/93	24:00	Minn2
C274037	8/1/93	00:00	12/31/93	24:00	Minn2
W274037	8/1/93	00:00	12/31/93	24:00	Minn2
C274050	8/1/93	00:00	12/31/93	24:00	Minn2
W274050	8/1/93	00:00	12/31/93	24:00	Minn2

<b>SHEET 14</b> <b>LTPP TRAFFIC DATA</b> <b>LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</b>	*STATE ASSIGNED ID [ 4005 ]
	*STATE CODE [ 37 ]
	*SHRP SECTION ID [ 4037 ]

LOCATION Burnsville, MN I-35 E TYPE EQUIP. Bending Plate  
( 2 South Bound Lanes )  
MP # 89.76 MODEL # FRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
1/21/93		Hard drive failure. New drive installed 1/26/93.	Mark Novak	296 - 2607	
2/21/93		Reset params. Site was not saving vehicle. & was not deleting old-records.			
3/19/93		Clock was 1 hour fast. Reset.			
4/2/93		Lane 2, sensor 4 off.			
4/26/93		Lane 2 shut off.			
6/29/93		Replaced Bending Plate in Lane 2.	↓	↓	

SHEET 14  
LTPP TRAFFIC DATA

LOG OF CHANGES AT GPS TEST  
LOCATIONS WITH PERM. AVC OR WIM

\*STATE ASSIGNED ID [4005]

\*STATE CODE [27]

\*SHRP SECTION ID [4037]

LOCATION Burnsville, MN, I-35E

TYPE EQUIP. Bending Plate

MP # 89.76 (2 South Bound Lanes)

MODEL # TRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
8/6/93		Lane 1, Cell. #2 & #6 not working.			
9/10/93		All Bending Plates down.			
10/26/93		Replaced BP#1 & 2.			
11/30/93		Upgraded site software to 7.3.3.			
11/23/93					

<b>SHEET 14</b> <b>LTPP TRAFFIC DATA</b> <b>LOG OF CHANGES AT GPS TEST</b> <b>LOCATIONS WITH PERM. AVC OR WIM</b>	*STATE ASSIGNED ID [ <u>4005</u> ]
	*STATE CODE [ <u>37</u> ]
	*SHRP SECTION ID [ <u>4037</u> ]

LOCATION Burnsville, MN I-35E TYPE EQUIP. Bending Plate  
(2 South Bound Lanes)  
 MP # 89.76 MODEL # IKO

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
1/21/93		Hard drive failure. New drive installed 1/26/93.	Mark Novak	296 - 2607	
2/21/93		Reset params. Site was not saving vehicle & was not deleting old-records.			
3/19/93		Clock was 1 hour fast. Reset.			
4/2/93		Lane 2, sensor 4 off.			
4/26/93		Lane 2 shut off.			
6/29/93		Replaced Bending Plate in Lane 2.	↓	↓	