

C271016	1/1/93	00:00	7/31/93	24:00	Minn2
W271016	1/1/93	00:00	7/31/93	24:00	Minn2
C274040	1/1/93	00:00	7/31/93	24:00	Minn2
W274040	1/1/93	00:00	7/31/93	24:00	Minn2
C271087	1/1/93	00:00	7/31/93	24:00	Minn2
W271087	1/1/93	00:00	7/31/93	24:00	Minn2
C274054	1/1/93	00:00	7/31/93	24:00	Minn2
W274054	1/1/93	00:00	7/31/93	24:00	Minn2

NAME OF PREPARER: Vicky Sarner
DATE PREPARED: December 16, 1993

PHONE NO.: 612-296-8526

C271016	8/1/93	00:00	12/31/93	24:00	Minn2
W271016	8/1/93	00:00	12/31/93	24:00	Minn2
C274040	8/1/93	00:00	12/31/93	24:00	Minn2
W274040	8/1/93	00:00	12/31/93	24:00	Minn2
C271087	9/1/93	00:00	12/31/93	24:00	Minn2
W271087	9/1/93	00:00	12/31/93	24:00	Minn2
C274054	9/1/93	00:00	12/31/93	24:00	Minn2
W274054	9/1/93	00:00	12/31/93	24:00	Minn2

NAME OF PREPARER: Vicky Sarner
DATE PREPARED: March 28, 1994

PHONE NO.: 612-296-8526

SHEET 14 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[4008]
	*STATE CODE	[37]
	*SHRP SECTION ID	[4040]

*SHRP SECTION ID [4040]

MP # _____ MODEL # TRD

MP # _____ MODEL # FRE _____

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
2/22/93		Hard drive failure.	Mark Novak	296-2607	
3/19/93		Backup and on-line.			
3/19/93		Lane 2 Sensor 3 Bending Plate out.			
6/24/93		Sensor 4 Bending Plate out.	↓	↓	

**LOG OF CHANGES AT GPS TEST
LOCATIONS WITH PERM. AVC OR WIM**

*SHRP SECTION ID [4040]

MP # _____ MODEL # _____ ³IRO

[illegible]

SHEET 14

LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM

*STATE ASSIGNED ID [4008]

*STATE CODE [27]

*SHRP SECTION ID [4040]

LOCATION US 2 Deer River, MN TYPE EQUIP. Bending Plate

MP # _____ MODEL # 7N _____[illegible]

LOG OF CHANGES AT GPS TEST
LOCATIONS WITH PERM. AVC OR WIM

*SHRP SECTION ID [4040]

LOCATION Deer River US-2 TYPE EQUIP. Bending Plate

MP # 172.21 MODEL # IND

[illegible]

LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM

•SHRP SECTION ID [4040]

MP # _____ MODEL # IRD

[illegible]