


RECEIVED OCT 28 1991

SHEET 1  
LTPP TRAFFIC DATA  
SUMMARY TRANSMITTAL FORM

\*STATE ASSIGNED ID [3666]  
\*STATE CODE [28]  
\*SHRP SECTION ID [3019]  
3019



STATE OR PROVINCE MS COUNTY TISHOMINGO  
HIGHWAY ROUTE NO. US 72 MILEPOST# 11.1  
NEAREST CITY/TOWN 3MI E OF IUKA NEAREST INTERSECTION 5MI E OF MS25  
FUNCTIONAL CLASS 2 NO. LANES EACH DIRECTION 2 TOTAL NO. LANES 4  
DIRECTION OF TRAVEL GPS LANE W DATE OPENED TO TRAF. 10-21-84  
FIPS COUNTY CODE 141 FHWA STATION IDENTIFICATION NO. \_\_\_\_\_  
HPMS SAMPLE NO. 711000010000 HPMS SUBDIVISION NO. \_\_\_\_\_  
TYPE OF PAVEMENT: AC \_\_\_\_\_ PCC ☒ OTHER \_\_\_\_\_  
CONTROL OF ACCESS: YES \_\_\_\_\_ NO ☒ MEDIAN: YES ☒ NO \_\_\_\_\_  
CURRENT SURROUNDING DEVELOPMENT:  
URBAN \_\_\_\_\_ SUBURBAN \_\_\_\_\_ RURAL ☒  
HAS INTENSITY OF ROADSIDE DEVELOPMENT INCREASED OVER PAST 10 YEARS?  
YES \_\_\_\_\_ NO ☒  
IF YES, DESCRIBE CHANGES \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

NOTE: ATTACH ALL RELATED FORMS AND COUNT DATA AND SUBMIT TO THE  
SHRP REGIONAL OFFICE. ATTACH MAP INDICATING THE LOCATION OF  
EACH TRAFFIC COUNT, VEHICLE CLASSIFICATION COUNT, OR WEIGHT  
STATION RELATIVE TO THIS GPS TEST SECTION.

|                        |               |
|------------------------|---------------|
| NAME OF PREPARER _____ | PHONE # _____ |
| DATE PREPARED _____    |               |

RECEIVED OCT 28 1991

|  |                    |        |
|--|--------------------|--------|
| <p align="center">SHEET 1</p> <p align="center"><b>LTPP TRAFFIC DATA</b></p> <p align="center"><b>SUMMARY TRANSMITTAL FORM</b></p> | *STATE ASSIGNED ID | 131121 |
|  | *STATE CODE        | 1281   |
|  | *SHRP SECTION ID   | 130191 |
|  |                    | 3018   |

STATE OR PROVINCE MS COUNTY TISHOMINGO

HIGHWAY ROUTE NO. US 72 MILEPOST# 11.1

NEAREST CITY/TOWN 3MI E OF IUKA NEAREST INTERSECTION 5MI E OF MS25

FUNCTIONAL CLASS 2 NO. LANES EACH DIRECTION 2 TOTAL NO. LANES 4

DIRECTION OF TRAVEL GPS LANE W DATE OPENED TO TRAF. 10-01-84

FIPS COUNTY CODE 141 FHWA STATION IDENTIFICATION NO. \_\_\_\_\_

HPMS SAMPLE NO. 711000010000 HPMS SUBDIVISION NO. \_\_\_\_\_

TYPE OF PAVEMENT: AC \_\_\_\_\_ PCC ☒ OTHER \_\_\_\_\_

CONTROL OF ACCESS: YES \_\_\_\_\_ NO ☒ MEDIAN: YES ☒ NO \_\_\_\_\_

CURRENT SURROUNDING DEVELOPMENT:

URBAN \_\_\_\_\_ SUBURBAN \_\_\_\_\_ RURAL ☒

HAS INTENSITY OF ROADSIDE DEVELOPMENT INCREASED OVER PAST 10 YEARS?

YES \_\_\_\_\_ NO ☒

IF YES, DESCRIBE CHANGES \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**NOTE:** ATTACH ALL RELATED FORMS AND COUNT DATA AND SUBMIT TO THE SHRP REGIONAL OFFICE. ATTACH MAP INDICATING THE LOCATION OF EACH TRAFFIC COUNT, VEHICLE CLASSIFICATION COUNT, OR WEIGHT STATION RELATIVE TO THIS GPS TEST SECTION.

|                        |               |
|------------------------|---------------|
| NAME OF PREPARER _____ | PHONE # _____ |
| DATE PREPARED _____    |               |

RECEIVED AUG 10 1992

SHEET 11  
LTPP TRAFFIC DATA

VOLUME DATA  
TRANSMITTAL FORM

\*STATE ASSIGNED ID [#018]

\*STATE CODE [28]

\*SHRP SECTION ID [3018]

HIGHWAY RT. NO. (THIS COUNT) US 72 MILEPOST NO. (THIS COUNT) NA

LOCATION (THIS COUNT) Iuka, Tishomingo County

FILENAME V283018.F12 DIST/TAPE ID SHRP No. 1

BEGINNING DATE 4-1-92 BEGINNING TIME 0 hour A.M.

ENDING DATE 6-30-92 ENDING TIME 24 hour P.M.

TYPE OF COUNT: TWO-WAY X ONE-WAY        SPS LANES       

COUNT DURATION 3 [ ] HOURS [ ] DAYS [X] MONTHS

TYPE OF SENSOR        ROAD TUBES X PIEZO CABLE

       PIEZO FILM        LOOPS        OTHER       

EQUIPMENT MANUFACTURER/MODEL # PAT - DAW 100

AXLE CORRECTION FACTOR N/A STANDARD DEV. OF FACTOR N/A

MONTHLY/SEASONAL FACTOR N/A STANDARD DEV. OF FACTOR N/A

DAY-OF-WEEK FACTOR N/A STANDARD DEV. OF FACTOR N/A

OTHER FACTOR N/A STANDARD DEV. OF FACTOR N/A  
SPECIFY       

DISTRIBUTION FACTOR FOR GPS LANE N/A  
(WHEN NOT AVAILABLE FROM ACTUAL COUNT DATA.)

SOURCE OF GPS LANE DISTRIBUTION FACTOR ESTIMATE       

COMMENTS: Day 4-7-92 missing.  
Day 4-23-92, hours 1-9 missing.  
Day 5-14-92, hour 16 missing.

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER Carolyn R. Thornton PHONE # 601-944-9142  
DATE PREPARED 8-1-92

SHEET 11  
LTPP TRAFFIC DATAVOLUME DATA  
TRANSMITTAL FORM

\*STATE ASSIGNED ID [#018]

\*STATE CODE [28]

\*SHRP SECTION ID [3018]

HIGHWAY RT. NO. (THIS COUNT) US 72 MILEPOST NO. (THIS COUNT) NALOCATION (THIS COUNT) Iuka, Tishomingo CountyFILENAME V283018.I12 DIST/TAPE ID SHRP No. 1BEGINNING DATE 7-1-92 BEGINNING TIME 0 hour A.M.ENDING DATE 9-30-92 ENDING TIME 24 hour P.M.TYPE OF COUNT: TWO-WAY X ONE-WAY        SPS LANES       COUNT DURATION 3 [ ] HOURS [ ] DAYS [X] MONTHSTYPE OF SENSOR        ROAD TUBES X PIEZO CABLE       PIEZO FILM        LOOPS        OTHER       EQUIPMENT MANUFACTURER/MODEL # PAT - DAW 100AXLE CORRECTION FACTOR N/A STANDARD DEV. OF FACTOR N/AMONTHLY/SEASONAL FACTOR N/A STANDARD DEV. OF FACTOR N/ADAY-OF-WEEK FACTOR N/A STANDARD DEV. OF FACTOR N/AOTHER FACTOR N/A STANDARD DEV. OF FACTOR N/A  
SPECIFY       DISTRIBUTION FACTOR FOR GPS LANE N/A  
(WHEN NOT AVAILABLE FROM ACTUAL COUNT DATA.)SOURCE OF GPS LANE DISTRIBUTION FACTOR ESTIMATE       COMMENTS: Days 7-22 through 7-24, 7-29, 7-30 missing.

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER Carolyn R. Thornton PHONE # 601-944-9142  
DATE PREPARED 10-22-92

SHEET 11  
LTPP TRAFFIC DATA

VOLUME DATA  
TRANSMITTAL FORM

\*STATE ASSIGNED ID [#018]  
\*STATE CODE [28]  
\*SHRP SECTION ID [3018]

HIGHWAY RT. NO. (THIS COUNT) US 72 MILEPOST NO. (THIS COUNT) NA

LOCATION (THIS COUNT) Iuka, Tishomingo County

FILENAME V283018.L12 DIST/TAPE ID SHRP No. 1

BEGINNING DATE 10-1-92 BEGINNING TIME 0 hour A.M.

ENDING DATE 12-31-92 ENDING TIME 24 hour P.M.

TYPE OF COUNT: TWO-WAY X ONE-WAY        SPS LANES       

COUNT DURATION 3 [ ] HOURS [ ] DAYS [X] MONTHS

TYPE OF SENSOR        ROAD TUBES X PIEZO CABLE

       PIEZO FILM        LOOPS        OTHER       

EQUIPMENT MANUFACTURER/MODEL # PAT - DAW 100

AXLE CORRECTION FACTOR N/A STANDARD DEV. OF FACTOR N/A

MONTHLY/SEASONAL FACTOR N/A STANDARD DEV. OF FACTOR N/A

DAY-OF-WEEK FACTOR N/A STANDARD DEV. OF FACTOR N/A

OTHER FACTOR N/A STANDARD DEV. OF FACTOR N/A

SPECIFY       

DISTRIBUTION FACTOR FOR GPS LANE N/A  
(WHEN NOT AVAILABLE FROM ACTUAL COUNT DATA.)

SOURCE OF GPS LANE DISTRIBUTION FACTOR ESTIMATE       

COMMENTS:       

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER Carolyn R. Thornton PHONE # 601-944-9142  
DATE PREPARED 1-13-93

SHEET 11  
LTPP TRAFFIC DATAVOLUME DATA  
TRANSMITTAL FORM

\*STATE ASSIGNED ID [#018]

\*STATE CODE [28]

\*SHRP SECTION ID [3019]

HIGHWAY RT. NO. (THIS COUNT) US 72 MILEPOST NO. (THIS COUNT) NALOCATION (THIS COUNT) Iuka, Tishomingo CountyFILENAME V283019.C13 DIST/TAPE ID SHRP No. 1BEGINNING DATE 1-1-93 BEGINNING TIME 0 hour A.M.ENDING DATE 3-31-93 ENDING TIME 24 hour P.M.TYPE OF COUNT: TWO-WAY X ONE-WAY        SPS LANES       COUNT DURATION 80 [ ] HOURS [X] DAYS [ ] MONTHSTYPE OF SENSOR        ROAD TUBES X PIEZO CABLE       PIEZO FILM        LOOPS        OTHER       EQUIPMENT MANUFACTURER/MODEL # PAT - DAW 100AXLE CORRECTION FACTOR N/A STANDARD DEV. OF FACTOR N/AMONTHLY/SEASONAL FACTOR N/A STANDARD DEV. OF FACTOR N/ADAY-OF-WEEK FACTOR N/A STANDARD DEV. OF FACTOR N/AOTHER FACTOR N/A STANDARD DEV. OF FACTOR N/A  
SPECIFY       DISTRIBUTION FACTOR FOR GPS LANE N/A  
(WHEN NOT AVAILABLE FROM ACTUAL COUNT DATA.)SOURCE OF GPS LANE DISTRIBUTION FACTOR ESTIMATE       COMMENTS: Hours 2-23 missing on 3-28-93.

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER Carolyn R. Thornton PHONE # 601-944-9142  
DATE PREPARED 4-15-93

SHEET 11  
LTPP TRAFFIC DATAVOLUME DATA  
TRANSMITTAL FORM

\*STATE ASSIGNED ID [#018]

\*STATE CODE [28]

\*SHRP SECTION ID [3018]

HIGHWAY RT. NO. (THIS COUNT) US 72 MILEPOST NO. (THIS COUNT) NALOCATION (THIS COUNT) Iuka, Tishomingo CountyFILENAME V283018.C13 DIST/TAPE ID SHRP No. 1BEGINNING DATE 1-1-93 BEGINNING TIME 0 hour A.M.ENDING DATE 3-31-93 ENDING TIME 24 hour P.M.TYPE OF COUNT: TWO-WAY X ONE-WAY        SPS LANES       COUNT DURATION 80 [ ] HOURS [X] DAYS [ ] MONTHSTYPE OF SENSOR        ROAD TUBES X PIEZO CABLE       PIEZO FILM        LOOPS        OTHER       EQUIPMENT MANUFACTURER/MODEL # PAT - DAW 100AXLE CORRECTION FACTOR N/A STANDARD DEV. OF FACTOR N/AMONTHLY/SEASONAL FACTOR N/A STANDARD DEV. OF FACTOR N/ADAY-OF-WEEK FACTOR N/A STANDARD DEV. OF FACTOR N/AOTHER FACTOR N/A STANDARD DEV. OF FACTOR N/A  
SPECIFY       DISTRIBUTION FACTOR FOR GPS LANE N/A  
(WHEN NOT AVAILABLE FROM ACTUAL COUNT DATA.)SOURCE OF GPS LANE DISTRIBUTION FACTOR ESTIMATE       COMMENTS: Hours 2-23 missing on 3-28-93.

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER Carolyn R. Thornton PHONE # 601-944-9142  
DATE PREPARED 4-15-93

RECEIVED SEP 20 2000

|   |                             |
|---|-----------------------------|
| SHEET 15<br>LTPP TRAFFIC DATA<br><br>LOG OF CHANGES AT GPS TEST<br>LOCATION WITH PERM. AVC OR WIM | *STATE ASSIGNED ID[ 018 ]   |
|   | *STATE CODE [ 28 ]          |
|   | *SHRP SECTION ID [ 3018/19] |

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

| DATE OF CHANGE  | TIME OF CHANGE | DESCRIPTION OF CHANGE                | PERSON MAKING CHANGE | PHONE NUMBER   | NEW EQUIPMENT SERIAL NUMBER |
|-----------------|----------------|--------------------------------------|----------------------|----------------|-----------------------------|
| August 2, 2000  | 13:25          | Change piezo board.                  | Johnie Thomas        | (601) 359-1502 |                             |
| August 8, 2000  | 8:05           | Changed mother board.                | Johnie Thomas        | (601) 359-1502 |                             |
| August 15, 2000 | 9:30           | Change mother board, and loop board. | Johnie Thomas        | (601) 359-1502 |                             |
|                 |                |                                      |                      |                |                             |
|                 |                |                                      |                      |                |                             |
|                 |                |                                      |                      |                |                             |
|                 |                |                                      |                      |                |                             |



RECEIVED AUG 28 2000

|   |                             |
|---|-----------------------------|
| SHEET 15<br>LTPP TRAFFIC DATA<br><br>LOG OF CHANGES AT GPS TEST<br>LOCATION WITH PERM. AVC OR WIM | *STATE ASSIGNED ID[ 018 ]   |
|   | *STATE CODE [ 28 ]          |
|   | *SHRP SECTION ID [ 3018/19] |

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

| DATE OF CHANGE | TIME OF CHANGE | DESCRIPTION OF CHANGE                           | PERSON MAKING CHANGE | PHONE NUMBER   | NEW EQUIPMENT SERIAL NUMBER |
|----------------|----------------|---|----------------------|----------------|-----------------------------|
| July 5, 2000   | 12:00          | Replaced the battery.                           | Johnie Thomas        | (601) 359-1502 |                             |
| July 10, 2000  | 12:45          | Reset fuse of mother board, replace phone jack. | Johnie Thomas        | (601) 359-1502 |                             |
| July 19, 2000  | 16:35          | Replaced the battery.                           | Johnie Thomas        | (601) 359-1502 |                             |
| July 27, 2000  | 12:35          | Replaced piezo card.                            | Johnie Thomas        | (601) 359-1502 |                             |
|                |                |   |                      |                |                             |
|                |                |   |                      |                |                             |
|                |                |   |                      |                |                             |

RECEIVED JUL 24 2000

|   |                             |
|---|-----------------------------|
| SHEET 15<br>LTPP TRAFFIC DATA<br><br>LOG OF CHANGES AT GPS TEST<br>LOCATION WITH PERM. AVC OR WIM | *STATE ASSIGNED ID[ 018 ]   |
|   | *STATE CODE [ 28 ]          |
|   | *SHRP SECTION ID [ 3018/19] |

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

[illegible]

RECEIVED MAY 18 2000

|   |                                     |
|---|-------------------------------------|
| <b>SHEET 15</b><br><b>LTPP TRAFFIC DATA</b><br><br><b>LOG OF CHANGES AT GPS TEST</b><br><b>LOCATION WITH PERM. AVG OR WIM</b> | <b>*STATE ASSIGNED ID</b> [ 018 ]   |
|   | <b>*STATE CODE</b> [ 28 ]           |
|   | <b>*SHRP SECTION ID</b> [ 3018/19 ] |

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

| DATE OF CHANGE | TIME OF CHANGE | DESCRIPTION OF CHANGE                | PERSON MAKING CHANGE | PHONE NUMBER   | NEW EQUIPMENT SERIAL NUMBER |
|----------------|----------------|--------------------------------------|----------------------|----------------|-----------------------------|
| April 10, 2000 | 13:57          | Changed battery and reset the loops. | Johnie Thomas        | (601) 359-1502 |                             |
| April 26, 2000 | 12:00          | Changed battery.                     | Johnie Thomas        | (601) 359-1502 |                             |
|                |                |                                      |                      |                |                             |
|                |                |                                      |                      |                |                             |
|                |                |                                      |                      |                |                             |
|                |                |                                      |                      |                |                             |
|                |                |                                      |                      |                |                             |

RECEIVED MAR 27 2000

|   |                             |
|---|-----------------------------|
| SHEET 15<br>LTPP TRAFFIC DATA<br><br>LOG OF CHANGES AT GPS TEST<br>LOCATION WITH PERM. AVC OR WIM | *STATE ASSIGNED ID[ 018 ]   |
|   | *STATE CODE [ 28 ]          |
|   | *SHRP SECTION ID [ 3018/19] |

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

| DATE OF CHANGE    | TIME OF CHANGE | DESCRIPTION OF CHANGE | PERSON MAKING CHANGE | PHONE NUMBER   | NEW EQUIPMENT SERIAL NUMBER |
|-------------------|----------------|-----------------------|----------------------|----------------|-----------------------------|
| February 8, 2000  | 8:15           | Replaced battery.     | Johnie Thomas        | (601) 359-1502 |                             |
| February 15, 2000 | 13:40          | Changed battery.      | Johnie Thomas        | (601) 359-1502 |                             |
|                   |                |                       |                      |                |                             |
|                   |                |                       |                      |                |                             |
|                   |                |                       |                      |                |                             |
|                   |                |                       |                      |                |                             |
|                   |                |                       |                      |                |                             |

RECEIVED JAN 24 2000

|  |   |
|--|---|
| SHEET 15<br>LTPP TRAFFIC DATA                                | *STATE ASSIGNED ID[ 018 ]                           |
| LOG OF CHANGES AT GPS TEST<br>LOCATION WITH PERM. AVC OR WIM | *STATE CODE [ 28 ]<br>*SHRP SECTION ID [ 3018 & 19] |

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

[illegible]

|   |                             |
|---|-----------------------------|
| SHEET 15<br>LTPP TRAFFIC DATA<br><br>LOG OF CHANGES AT GPS TEST<br>LOCATION WITH PERM. AVC OR WIM | *STATE ASSIGNED ID[ 018 ]   |
|   | *STATE CODE [ 28 ]          |
|   | *SHRP SECTION ID [ 3018/19] |

LOCATION IUKA, TISHOMINGO COUNTYTYPE EQUIP. PATMP # N/AMODEL# DAW 100

| DATE OF CHANGE    | TIME OF CHANGE | DESCRIPTION OF CHANGE | PERSON MAKING CHANGE | PHONE NUMBER   | NEW EQUIPMENT SERIAL NUMBER |
|-------------------|----------------|-----------------------|----------------------|----------------|-----------------------------|
| November 2, 1999  | 9:30           | Changed battery.      | Johnie Thomas        | (601) 359-1502 |                             |
| November 17, 1999 | 10:40          | Changed battery.      | Johnie Thomas        | (601) 359-1502 |                             |
|                   |                |                       |                      |                |                             |
|                   |                |                       |                      |                |                             |
|                   |                |                       |                      |                |                             |
|                   |                |                       |                      |                |                             |
|                   |                |                       |                      |                |                             |

RECEIVED SEP 07 1999

|   |                               |
|---|-------------------------------|
| SHEET 15<br>LTPP TRAFFIC DATA<br><br>LOG OF CHANGES AT GPS TEST<br>LOCATION WITH PERM. AVC OR WIM | *STATE ASSIGNED ID[ 018 ]     |
|   | *STATE CODE [ 28 ]            |
|   | *SHRP SECTION ID [ 3018 & 19] |

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

| DATE OF CHANGE | TIME OF CHANGE | DESCRIPTION OF CHANGE               | PERSON MAKING CHANGE | PHONE NUMBER   | NEW EQUIPMENT SERIAL NUMBER |
|----------------|----------------|-------------------------------------|----------------------|----------------|-----------------------------|
| July 1, 1999   | 15:00          | REPLACED BATTERY.                   | JOHNIE THOMAS        | (601) 359-1502 |                             |
| July 21, 1999  | 14:55          | CHANGED THE MODEM.                  | JOHNIE THOMAS        | (601) 359-1502 |                             |
| July 27, 1999  | 14:20          | CHANGED THE BATTERY AND LOOP BOARD. | JOHNIE THOMAS        | (601) 359-1502 |                             |
| July 28, 1999  | 8:30           | CHANGE THE BATTERY.                 | JOHNIE THOMAS        | (601) 359-1502 |                             |
|                |                |                                     |                      |                |                             |
|                |                |                                     |                      |                |                             |
|                |                |                                     |                      |                |                             |

|   |                             |
|---|-----------------------------|
| SHEET 15<br>LTPP TRAFFIC DATA<br><br>LOG OF CHANGES AT GPS TEST<br>LOCATION WITH PERM. AVC OR WIM | *STATE ASSIGNED ID[ 018 ]   |
|   | *STATE CODE [ 28 ]          |
|   | *SHRP SECTION ID [ 3018&19] |

LOCATION IUKA, TISHOMINGO COUNTYTYPE EQUIP. PATMP # N/AMODEL# DAW 100

| DATE OF CHANGE | TIME OF CHANGE | DESCRIPTION OF CHANGE                        | PERSON MAKING CHANGE | PHONE NUMBER   | NEW EQUIPMENT SERIAL NUMBER |
|----------------|----------------|--|----------------------|----------------|-----------------------------|
| June 2, 1999   | 12:00          | REPLACED BATTERY AND CHANGE THE PIEZO BOARD. | JOHNIE THOMAS        | (601) 359-1502 |                             |
| June 8, 1999   | 12:45          | RESET MODEM.                                 | JOHNIE THOMAS        | (601) 359-1502 |                             |
|                |                |  |                      |                |                             |
|                |                |  |                      |                |                             |
|                |                |  |                      |                |                             |
|                |                |  |                      |                |                             |
|                |                |  |                      |                |                             |



## LTPP TRAFFIC DATA

**LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM**

STATE ASSIGNED ID [ 018 ]

STATE CODE [28]

SHRP SECTION ID 130 18.

LOCATION TRICA, TISHOMINGO CO. TYPE EQUIP. PAT

MP # NA

MODEL # DAW 100

RECEIVED SEP 11 1993

[illegible]

**LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM**

SHRP SECTION ID [3078]

RECEIVED JAN 20 1998

MP # NA

MODEL # DAW 100

[illegible]

**LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM**

SHRP SECTION ID [3048]

MP # NA

MODEL # DAW 100

RECEIVED OCT 14 1997

[illegible]

# LTPP TRAFFIC DATA

## LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM

STATE ASSIGNED ID [ 018 ]

STATE CODE [ 28 ]

SHRP SECTION ID [ 3018 ]

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PAT

MP # NA MODEL # DAW 100

| DATE OF<br>CHANGE | TIME OF<br>CHANGE | DESCRIPTION OF CHANGE                     | PERSON MAKING<br>CHANGE | PHONE #         | NEW EQUIP.<br>SERIAL # |
|-------------------|-------------------|---|-------------------------|-----------------|------------------------|
| 1-10-96           | 8:32              | REPLACED OLD BATTERY,<br>WITH NEWER MODEL | ALAN D HATCH            | 601<br>359-7685 | N/A                    |
| 11                | 11                | (RESET OK)                                | 11                      | 11              | 11                     |
|                   |                   |   |                         |                 |                        |
|                   |                   |   |                         |                 |                        |
|                   |                   |   |                         |                 |                        |
|                   |                   |   |                         |                 |                        |
|                   |                   |   |                         |                 |                        |
|                   |                   |   |                         |                 |                        |
|                   |                   |   |                         |                 |                        |
|                   |                   |   |                         |                 |                        |
|                   |                   |   |                         |                 |                        |

RECEIVED APR 19 1996

|  |                                  |
|--|----------------------------------|
| <b>SHEET 15</b><br><b>LTPP TRAFFIC DATA</b><br><b>LOG OF CHANGES AT GPS TEST</b><br><b>LOCATIONS WITH PERM. AVC OR WIM</b> | STATE ASSIGNED ID [ <u>018</u> ] |
|  | STATE CODE [ <u>28</u> ]         |
|  | SHRP SECTION ID [ <u>3018</u> ]  |

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PAT

MP # NA MODEL # DAW 100

| DATE OF CHANGE | TIME OF CHANGE | DESCRIPTION OF CHANGE  | PERSON MAKING CHANGE | PHONE #  | NEW EQUIP. SERIAL # |
|----------------|----------------|--|----------------------|----------|---------------------|
| 8-2-94         | 16:34          | PIEZO ANALYZER BOARD - BURN O.I.T SENT TO FACTORY FOR REPAIR. UNIT OUT OF ORDER, PIEZO BOARD WAS | ALAN D. HATCH        | 359 7685 | N/A                 |
| 11             | 11             | NOT AVAILABLE (UNIT SHUT DOWN)   | 11                   | 11       | 11                  |
|                |                |  |                      |          |                     |
|                |                |  |                      |          |                     |
|                |                |  |                      |          |                     |
|                |                |  |                      |          |                     |
|                |                |  |                      |          |                     |
|                |                |  |                      |          |                     |
|                |                |  |                      |          |                     |

RECEIVED OCT 20 1994

|  |                                  |
|--|----------------------------------|
| <b>SHEET 15</b><br><b>LTPP TRAFFIC DATA</b><br><b>LOG OF CHANGES AT GPS TEST</b><br><b>LOCATIONS WITH PERM. AVC OR WIM</b> | STATE ASSIGNED ID [ <u>018</u> ] |
|  | STATE CODE [ <u>28</u> ]         |
|  | SHRP SECTION ID [ <u>3018</u> ]  |

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PAT

MP # NA MODEL # DAW 100

| DATE OF CHANGE | TIME OF CHANGE | DESCRIPTION OF CHANGE  | PERSON MAKING CHANGE | PHONE #     | NEW EQUIP. SERIAL # |
|----------------|----------------|--|----------------------|-------------|---------------------|
| 4-20-94        | 16:44          | Loop Analyzer Board Malfunction<br>Installed Good Board Unit Back in Order | ALAN D. Hatch        | 944<br>9142 | 3119                |
| 6-14-94        | 15:30          | INSTALLED CHARGED BATTERY<br>UNIT BACK IN ORDER                            | ALAN D. Hatch        | CC          | N/A                 |
|                |                |  |                      |             |                     |
|                |                |  |                      |             |                     |
|                |                |  |                      |             |                     |
|                |                |  |                      |             |                     |
|                |                |  |                      |             |                     |
|                |                |  |                      |             |                     |
|                |                |  |                      |             |                     |

RECEIVED JUL 20 1994

|                                |                             |
|--------------------------------|-----------------------------|
| SHEET 15                       | *STATE ASSIGNED ID[ 018 ]   |
| LTPP TRAFFIC DATA              |                             |
|                                | *STATE CODE [ 28 ]          |
| LOG OF CHANGES AT GPS TEST     |                             |
| LOCATION WITH PERM. AVC OR WIM | *SHRP SECTION ID [ 3018/19] |

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. \_\_\_\_\_ PAT \_\_\_\_\_

MP # N/A

MODEL#                      DAW 100

[illegible]

|   |                                    |
|---|------------------------------------|
| <b>SHEET 15</b><br><b>LTPP TRAFFIC DATA</b><br><br><b>LOG OF CHANGES AT GPS TEST</b><br><b>LOCATION WITH PERM. AVC OR WIM</b> | <b>*STATE ASSIGNED ID[ 018 ]</b>   |
|   | <b>*STATE CODE [ 28 ]</b>          |
|   | <b>*SHRP SECTION ID [ 3018/19]</b> |

LOCATION IUKA, TISHOMINGO COUNTYTYPE EQUIP. PATMP # N/AMODEL# DAW 100

| DATE OF CHANGE | TIME OF CHANGE | DESCRIPTION OF CHANGE | PERSON MAKING CHANGE | PHONE NUMBER   | NEW EQUIPMENT SERIAL NUMBER |
|----------------|----------------|-----------------------|----------------------|----------------|-----------------------------|
| May 16, 2000   | 12:30          | Changed the battery.  | Johnie Thomas        | (601) 359-1502 |                             |
| May 31, 2000   | 13:45          | Changed the battery.  | Johnie Thomas        | (601) 359-1502 |                             |
|                |                |                       |                      |                |                             |
|                |                |                       |                      |                |                             |
|                |                |                       |                      |                |                             |
|                |                |                       |                      |                |                             |
|                |                |                       |                      |                |                             |



RECEIVED APR 24 2000

|   |                                    |
|---|------------------------------------|
| <b>SHEET 15</b><br><b>LTPP TRAFFIC DATA</b><br><br><b>LOG OF CHANGES AT GPS TEST</b><br><b>LOCATION WITH PERM. AVC OR WIM</b> | <b>*STATE ASSIGNED ID[ 018 ]</b>   |
|   | <b>*STATE CODE [ 28 ]</b>          |
|   | <b>*SHRP SECTION ID [ 3018/19]</b> |

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

| DATE OF CHANGE | TIME OF CHANGE | DESCRIPTION OF CHANGE   | PERSON MAKING CHANGE | PHONE NUMBER   | NEW EQUIPMENT SERIAL NUMBER |
|----------------|----------------|---|----------------------|----------------|-----------------------------|
| March 6, 2000  | 15:40          | Replaced the battery.   | Johnie Thomas        | (601) 359-1502 |                             |
| March 22, 2000 | 9:30           | Replaced the piezo board, changed the overall sensitivity and front axle. | Johnie Thomas        | (601) 359-1502 |                             |
|                |                |   |                      |                |                             |
|                |                |   |                      |                |                             |
|                |                |   |                      |                |                             |
|                |                |   |                      |                |                             |
|                |                |   |                      |                |                             |

RECEIVED JAN 16 1996

**SHEET 15**

**LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM**

STATE ASSIGNED ID [ \_ 0 1 8 ]

STATE CODE [ 28 ]

SHRP SECTION ID [3048]

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PAT

MP # NA MODEL # DAW 100

[illegible]

|  |                           |
|--|---------------------------|
| <b>SHEET 15</b><br><b>LTPP TRAFFIC DATA</b><br><b>LOG OF CHANGES AT GPS TEST</b><br><b>LOCATIONS WITH PERM. AVC OR WIM</b> | STATE ASSIGNED ID [ 018 ] |
|  | STATE CODE [ 28 ]         |
|  | SHRP SECTION ID [ 3018 ]  |

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PAT

MP # NA MODEL # DAW 100

| DATE OF CHANGE | TIME OF CHANGE | DESCRIPTION OF CHANGE   | PERSON MAKING CHANGE | PHONE #         | NEW EQUIP. SERIAL #                         |
|----------------|----------------|---|----------------------|-----------------|---|
| 7-10-95        | 16:34 PM       | MALFUNCTION IN PIEZO ANALYZER BOARD (OVERHEATED). LOOP BOARD LANES 1 AND 2 SIGNAL LOSS. | ALAN D. HATCH        | 601<br>359-7685 | PIEZO BOARD<br>772<br>LOOP BOARD<br>665     |
| 11             | 11             | REPLACED WITH GOOD BOARDS<br>RESET  | 11                   | 11              | 11  |
| 7-18-95        | 10:58 AM       | MALFUNCTION IN PIEZO ANALYZER BOARD (OVERHEATED). LOOP BOARD LANE 1 SIGNAL LOSS.        | 11                   | 11              | PIEZO BOARD<br>9300141<br>LOOP BOARD<br>590 |
| 11             | 11             | REPLACED WITH GOOD BOARDS<br>RESET  | 11                   | 11              | 11  |
|                |                |   |                      |                 |   |
|                |                |   |                      |                 |   |
|                |                |   |                      |                 |   |
|                |                |   |                      |                 |   |
|                |                |   |                      |                 |   |

SHEET 15

## LTPP TRAFFIC DATA

LOG OF CHANGES AT GPS TEST  
LOCATIONS WITH PERM. AVC OR WIM

STATE ASSIGNED ID [ 018 ]

STATE CODE [ 28 ]

SHRP SECTION ID [ 3018 ]

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PATMP # NA MODEL # DAW 100

| DATE OF<br>CHANGE | TIME OF<br>CHANGE | DESCRIPTION OF CHANGE  | PERSON MAKING<br>CHANGE | PHONE #            | NEW EQUIP.<br>SERIAL # |
|-------------------|-------------------|--|-------------------------|--------------------|------------------------|
| 4-18-95           | 15:30             | CHANGED BATTERY AND COLLECTED<br>DATA UNIT BACK IN ORDER (OK)<br>NOISE IN PHONE LINE (REPAIRED-OK) | ALAN D. HATCH           | 601<br>359<br>7685 | NC                     |
|                   |                   |  |                         |                    |                        |
|                   |                   |  |                         |                    |                        |
|                   |                   |  |                         |                    |                        |
|                   |                   |  |                         |                    |                        |
|                   |                   |  |                         |                    |                        |
|                   |                   |  |                         |                    |                        |
|                   |                   |  |                         |                    |                        |
|                   |                   |  |                         |                    |                        |

RECEIVED AUG - 2 1995