

Year 2007

0600

SHEET 14 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	STATE ASSIGNED ID	3903
	STATE CODE	46
	SHRP SECTION ID	0601

LOCATION West of Groton TYPE EQUIP. PAT Blending Plate
 MILEPOST NO. MRM 307 MODEL # DAW 190

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE	NEW EQUIP. SERIAL#
07/22/1992		Installation of DD 200	IRD-Rep & Blair Lunde		NA
Oct-93		Equipment Repairs			
06/26/1996		Replace all four Bending Plates Update wiring, lightning protection, and field software	Lunde & Becker Mike Haug from IRD		
08/22/1996		Computer was sent in for repairs and updating software	Lunde		
12/11/1996		Reinstall the computer.	Lunde & Becker		
07/07/1997		Changed the site number in the field computer.	Lunde & Engelmann		
Oct-00		Installed PAT DAW 190 System			
04/10/2001		Replace Eprom	Dan LeBlanc(Pat)		
06/19/2001	A.M.	Replace Eprom	Dan Strand Darin Charlson	(605) 773-3871 (605) 773-5026	
08/08/2001	3:15 PM	The calibration process was performed at this site in the month of July. The Sen- sitivity value in Mode 0 was changed for lane 1.	Darin Charlson	(605) 773-5026	
10/22/2001	A.M.	Replace Eprom	Dan Strand Jon Becker	(605) 773-3871 (605) 773-6242	
01/30/2003	A.M.	Replace temperature sensor	Darin Charlson Jon Becker	(605) 773-5026 (605) 773-6242	
05/29/2003	A.M.	Replace Eprom	Darin Charlson Jon Becker	(605) 773-5026 (605) 773-6242	
07/20/2004		The calibration process was performed at this site in the month of July.	Darin Charlson Jon Becker	(605) 773-5026 (605) 773-6242	
02/21/2006	PM	Replace Eprom - avoid system locking up.	Darin Charlson Jon Becker	(605) 773-5026 (605) 773-6242	
05/29/2007	A.M.	Maintenance check - replaced splice for leading bending plate lane 2 WB. Leading bending plate lane 1 WB is bad.	Darin Charlson Jon Becker	(605) 773-5026 (605) 773-6242	
08/15/2007		Replaced leading bending plate in the driving lane west bound.	Darin Charlson Jon Becker	(605) 773-5026 (605) 773-6242	
10/23/2007		Replaced trailing bending plate in the driving lane west bound.	Darin Charlson Jon Becker	(605) 773-5026 (605) 773-6242	

SHEET 13
TRAFFIC DATA FILES
TRANSMITTAL FORM

STATE South Dakota
STATE CODE 46

FILENAME	START DATE mm/dd/yy	START TIME hh:mm	END DATE mm/dd/yy	END TIME hh:mm	CLASS. SCHEME
C460601.C1h	01/01/2007	00:00	01/31/2007	23:59	FHWA
W460601.C1h	01/01/2007	00:00	01/31/2007	23:59	FHWA
C460601.D1h	02/01/2007	00:00	2/29/2007	23:59	FHWA
W460601.D1h	02/01/2007	00:00	2/29/2007	23:59	FHWA
C460601.E1h	03/01/2007	00:00	03/31/2007	23:59	FHWA
W460601.E1h	03/01/2007	00:00	03/31/2007	23:59	FHWA
C460601.F1h	04/01/2007	00:00	04/30/2007	23:59	FHWA
W460601.F1h	04/01/2007	00:00	04/30/2007	23:59	FHWA
C460601.G1h	05/01/2007	00:00	05/31/2007	23:59	FHWA
W460601.G1h	05/01/2007	00:00	05/31/2007	23:59	FHWA
C460601.H1h	06/01/2007	00:00	06/30/2007	23:59	FHWA
W460601.H1h	06/01/2007	00:00	06/30/2007	23:59	FHWA
C460601.I1h	07/01/2007	00:00	07/31/2007	23:59	FHWA
W460601.I1h	07/01/2007	00:00	07/31/2007	23:59	FHWA
C460601.J1h	08/01/2007	00:00	08/31/2007	23:59	FHWA
W460601.J1h	08/01/2007	00:00	08/31/2007	23:59	FHWA
C460601.K1h	09/01/2007	00:00	09/30/2007	23:59	FHWA
W460601.K1h	09/01/2007	00:00	09/30/2007	23:59	FHWA
C460601.L1h	10/01/2007	00:00	10/31/2007	23:59	FHWA
W460601.L1h	10/01/2007	00:00	10/31/2007	23:59	FHWA
C460601.M1h	11/01/2007	00:00	11/30/2007	23:59	FHWA
W460601.M1h	11/01/2007	00:00	11/30/2007	23:59	FHWA
C460601.N1h	12/01/2007	00:00	12/31/2007	23:59	FHWA
W460601.N1h	12/01/2007	00:00	12/31/2007	23:59	FHWA

PREPARED BY: Kenneth E. Marks
DATE PREPARED: 02/08/2008

PHONE #: (605) 773-3336