

Year 2005

SHEET 12	STATE ASSIGNED ID	[3910]
LTPP TRAFFIC DATA	STATE CODE	[46]
COLLECTION SITE	SHRP SECTION ID	[3010]
	EFFECTIVE DATE	[2005]

HIGHWAY RT. NO. 129 SBL MILEPOST NO. MRM 229.960

LOCATION North of Sisseston

VEHICLE CLASSIFICATION METHOD:	FHWA	X	OTHER	# BINS
--------------------------------	------	---	-------	--------

TYPE OF CLASSIFICATION EQUIPMENT: PORTABLE PERMANENT X

AVC EQUIPMENT MAKE/MODEL NO.

SENSOR TYPE

WEIGHT SCALE TYPE: PORT. WIM PERM. WIM X OTHER

EQUIPMENT MAKE/MODEL NO. PAT DAW 190

SENSOR TYPE Bending Plate

METHOD OF CALIBRATION: Intitial calibration was done with a 5 axle semi having known weights and axle spacings. System will use auto calibration algorithms on 5 axle semi's during system operation.

FREQUENCY OF CALIBRATION: Yearly using 5 axle semi's from traffic stream with indepent weights by Highway Patrol Static Scale

COMMENTS: Data for the months of January, August, September and October.
Other months of 2005 have been having problems with Bending Plate.

NAME OF PREPARER Kenneth E. Marks PHONE # (605) 773-3336
DATE PREPARED 2-23-06

Year 2005

<p>SHEET 14 LTPP TRAFFIC DATA</p> <p>LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>STATE ASSIGNED ID <u>3803</u> STATE CODE <u>46</u> SHRP SECTION ID <u>3010</u></p>
---	---

LOCATION South of Sisseston TYPE EQUIP. PAT Bending Plate

MILEPOST NO. MRM 229.96 MODEL # DAW 190

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE	NEW EQUIP. SERIAL#
Sep-99		Installation of DAW190 BP		(605) 698-4421	
4/10/2001		Replace Eprom	Dan LeBlanc(Pat)		
6/19/2001	A.M.	Replace Eprom	Dan Strand Darin Charlson	(605) 773-3871 (605) 773-5026	
5/1/2001		The calibration process was performed at this site in the month of May.	Dan Strand Darin Charlson	(605) 773-3871 (605) 773-5026	
10/22/2001	P.M.	Replace Eprom - The system quit recording on Wednesday the 10th of October.	Dan Strand Jon Becker	(605) 773-3871 (605) 773-6242	
5/29/2003	P.M.	Replace Eprom	Darin Charlson Jon Becker	(605) 773-5026 (605) 773-6242	
7/27/2004 7/28/2004		The calibration process was performed at this site in the month of July.	Jon Becker	(605) 773-5026 (605) 773-6242	
1/17/2005		Problems with Bending Plates	Jon Becker	(605) 773-5026 (605) 773-6242	