

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C )
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

File: 800.12.11.9.12

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
12/31/09		No Changes			

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C )
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

 LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

 MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
10/31/09		<b>No Changes</b>			

File: 800.12.11.9.12  
530200

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C )
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
09/08/09		Problem: Piezo #5 SB drive lane is not activating (starting around August 14th.) Disabled in software for now.	(HN)		
9/23/09	(10:15 - 11:15)	Problem: Sensor #5 SB was not activating. Found sensor chewed broken by "them." Re-spliced sensor. Tested OL.	(HN)		

File: 800,12.11.9.12

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C)
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
8/31/09		No Changes			

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C )
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
7/31/09		No Changes			

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C )
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

 LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

 MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
06/30/09		No Changes			

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C )
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

File: 800.12.11.9.12  
630201

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
05/18/09	(15:00 - 15:30)	Ritzville2-P7C Problem: Missing hours in data files (unit blanked out, then reset when contacted.) Replaced processor.	HN		

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

File: 800.12.11.8.12  
530200

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
3/25/09	(08:15 - 08:45)	<b>Ritzville2-P7C (08:15 -08:45)</b> Site inspected. Copied log and parameter files.	HN		