

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P17 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 1007 ]

LOCATION SR 221 TYPE EQUIP. Piezo (Class 1)

MP # 13.1 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
04/06/99		Found axle sensor not installed; installed IRD/WA default temp/weight autocal. NB piezo needs to be replaced.	RichRempfer		
04/08/99		Replaced #2 piezo NB.	Ken Lakey & crew		
04/12/99		Replaced #1 piezo in NB lane.	Ken Lakey & crew		
05/12/99		New axle sensor installed NB; recalibrated and balanced piezos.	Rich Rempfer		

<p align="center">SHEET 15</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P17 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 1007 ]

LOCATION SR 221 TYPE EQUIP. Piezo (Class 1)

MP # 13.1 MODEL # IRD 1060

[illegible]