

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P17 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 1007 ]

LOCATION SR 221 TYPE EQUIP. Piezo (Class 1)

MP # 13.1 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
					<b>9008-0627</b>
<b>02/20/01</b>		<u>Prosser WIM</u> Found axle sensor #2 (NB downstream) breaking up in roadway; disabled it in software. All Phillips sensors here. Pavement slightly rutten and in "fair" condition. Reset thresholds and calibrated. Good weights, beg. 2-21-01. RR KL	<b>RICH REMPFER</b>		