

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P04 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 3011 ]

LOCATION SR 5 TYPE EQUIP. Piezo (Class 1)

MP # 261.0 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PH ON E #	NEW EQUIP. SERIAL #
10/31/11		No Changes			
10/11/11		<p>HIGH IMPACT</p> <p>I-5 Northbound - DRIVER ALERT: Tuesday, Oct. 11 - Thursday, Oct. 13 - Crews will close the right lane of northbound I-5 at the Slater Road exit around the clock beginning at 6 a.m. Tuesday to 4 p.m. Thursday for concrete panel replacement. The on-ramp from Slater Rd. to northbound I-5 will also close. This work is weather dependent.</p> <p>Last Updated: 10/7/2011 9:38 AM</p> <p>At milepost 260 (Tom)</p>			

800.12.11.8.12

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [ P04 ]</p> <p>*STATE CODE [ 53 ]</p> <p>*SHRP SECTION ID [ 3011 ]</p>
---	--

LOCATION SR 5 TYPE EQUIP. Piezo (Class 1)MP # 261.0 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
9/6/11		<p><b>9/6/11 P04 – Ferndale</b> Recut sensor # 1 and sensor # 5. Hoang will enable in system and balance those sensors. (NC)</p> <p><b>9/6/11 P04 – Ferndale</b> Enabled and balanced sensors #1 and #5. Copied log and parameter files. (HN)</p>	Hoang		
9/22/11		<p><b>HIGHEST IMPACT</b> I-5 Both Directions - Update 7:59 AM : On I-5 northbound &amp; southbound at Lakeway Dr (MP 253) there is a collision blocking all lanes. Medical Aid, Fire Assistance, and the State Patrol have arrived on the scene. Last Updated: 9/22/2011 8:01 AM At milepost 253 Note***; webcam shows a liquid nitrogen tanker overturned in the Northbound lanes and leaking into the Southbound (Northbound was still closed at Lakeway Dr at 11:30am) (Tom)</p> <p>Truck crashes block I-5 near Bellingham BELLINGHAM, Wash. - Two separate truck accidents have closed I-5 in both directions near Bellingham. Transportation Department spokeswoman Kris Olson said a tanker carrying liquid nitrogen overturned in the northbound lanes and a semi jackknifed in the southbound lanes. The accidents happened before 8 a.m. Thursday within two miles of each other.</p>			

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [ P04 ]</p> <p>*STATE CODE [ 53 ]</p> <p>*SHRP SECTION ID [ 3011 ]</p>
---	--

LOCATION SR 5 TYPE EQUIP. Piezo (Class 1)

MP # 261.0 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
5/31/11		<b>No Changes</b>			
5/4/11		<p><b>Harley riders receive bad fuel at Ferndale station</b>            Posted on May 4, 2011 at 3:09 PM            BELLINGHAM, Wash. - When Garrit Vis revs up his Harley, he likes to hear the grumble of his engine beneath his seat.            That's not what he heard after filling up at a Ferndale gas station during a local charity ride.            "It just sputtered out on me," he said. "It felt like I was riding on one piston."            Vis and about 18 other riders all experienced the same problem. After returning to the station, it was determined that the gas they pumped from the premium unleaded tank (\$4.39/gallon) was diluted with water and filled with some kind of brown sludge.            "I wasn't going to go any further," said Rod Smithson. His Harley was also affected by the bad gas. Watered down fuel can be damaging to an engine.            Mount Baker Harley Davidson out of Bellingham picked the bikers up and took them to the shop. Vis says managers at the Shell station helped them siphon gas from their tanks.            The Shell station at the Silver Reef Casino (I-5 exit 260, 4 mi West (4876 Haxton Way) on Haxton Way is on Lummi Tribal land. Lummi leaders say the fuel delivered to them was filled with water. They say new fuel was put in the tank and the pumps are 100 percent operational again.            Lummi leaders say they are working with the tribe's insurance company to make sure affected customers are somehow reimbursed for any damages the bad gas may have caused.            Vic was billed \$112 to have his engine flushed and cleaned.            The company that delivers the fuel, McEvoy Oil, did not return phone calls for comment.            (Tom)</p>			

5/11/11		<p><b>MODERATE IMPACT</b></p> <p>I-5 Both Directions - The left lane of northbound I-5 near Ferndale will close Wednesday 5/11/11 from 9 a.m. to 1 p.m. for shoulder maintenance. The left lane of southbound I-5 will close Thursday 5/12/11 from 9 a.m. to 1 p.m. for the same work.</p> <p>At milepost 262 (Tom)</p>			
5/20/11		<p>Increased border traffic on Victoria Day weekend</p> <p>Associated Press - May 20, 2011 9:45 AM ET</p> <p>BLAINE, Wash. (AP) - The Customs and Border Protection agency is expecting a busy weekend at Washington border crossings as many Canadians head south for their 3-day Victoria Day Holiday (May 23) weekend.</p> <p>The agency says it's opening additional inspection lanes at crossings in Blaine and Sumas. (Tom)</p>			

800.12.11.8.12

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [ P04 ]</p> <p>*STATE CODE [ 53 ]</p> <p>*SHRP SECTION ID [ 3011 ]</p>
---	--

LOCATION SR 5 TYPE EQUIP. Piezo (Class 1)

MP # 261.0 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PH ON E #	NEW EQUIP. SERIAL #
3/2/11		Problem: SB sensor #5 intermittently not activated. Disable it for now.	HN		
3/30/11		Counter 1068 # 0305-8184, ZDX # 6097305 and power is full time. Completed site evaluations, needs j-box upgrades. Site photos and evaluation posted to Simms.	Matt H		

File: 800.12.11.8.12

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [ P04 ]</p> <p>*STATE CODE [ 53 ]</p> <p>*SHRP SECTION ID [ 3011 ]</p>
---	--

LOCATION SR 5 TYPE EQUIP. Piezo (Class 1)MP # 261.0 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
1/31/11		<b>No Changes</b>	Hoang		
1/7/11		<p>Alcoa to restart Ferndale's Intalco, 2 other smelting lines by Associated Press Posted on January 7, 2011 at 11:35 AM</p> <p>NEW YORK - Aluminum maker Alcoa said Friday it plans to restart three idled U.S. smelters, bringing back about 260 laid-off workers and hiring some new ones. Potlines will be restarted at the Massena East facility in Massena, N.Y.; Wenatchee Works in Malaga, Wash.; and Intalco in Ferndale, Wash., the company said in a statement. Alcoa said it would recall 95 laid-off workers and hire another 165 employees for the plants. The restarts, which already have begun, will help Alcoa meet expected growth in aluminum demand, and it will meet obligations to power companies in long-term, low-cost contracts, Alcoa's statement said.</p> <p>Power rates at Wenatchee and Massena are about 40 percent less than worldwide averages, the company said. The restarts will be powered by hydroelectric power.</p> <p>"We are pleased to bring jobs back and increase our economic impact in each of these communities," said Bob Wilt, president of Alcoa's U.S. primary products. "We believe this additional capacity will be absorbed in the market as Alcoa meets rising demand for light, strong and recyclable aluminum from customers around the world."</p> <p>The restarts should be finished in the first half of the year. After completion, Alcoa still will have 674,000 metric tons of idle factory capacity, the company's statement said. (Tom)</p>			