


<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [B03]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [3014]</p>
---	--

LOCATION SR 395 TYPE EQUIP. IRD Bending Plate

MP # 27.2 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
5/4/11		<p>Site inspected. Patched sensor #5. Copied log and parameter files. (HN)</p> <p>Called S/C Yakima TMC for a single right lane closure on SR-395 South bound lane # 1 from mile post 27 to mile post 29 @ 1217, phoned into kerri. Set up traffic control and work area. Assisted with patching sesors. Put away equipement. Picked up traffic control and cleared the lane @ 1304, phoned into Kerri. Went to Othello East. (Matt H – simms)</p>	hn		

1/14/11

Highway 395 overpass in Pasco damaged**By Bob Brawdy, Herald staff writer**

Chunks of concrete litter the southbound lanes of Highway 395 under the Court Street overpass Friday night after a semi-truck hauling an excavator hit it. The lanes were blocked until Department of Transportation snowplows cleared the larger debris from the outside lane so traffic could squeeze past. Three other vehicles were damaged by running over pieces of concrete or getting hit by the flying debris. Trooper Dave Bond of Washington State Patrol said the driver of the semi-truck would be cited for carrying a load over the legal height. DOT engineers are assessing the structural damage to the overpass girders.

PASCO -- Chunks of concrete littered the southbound lanes of Highway 395 under the Court Street overpass Friday night after a semi-truck hauling an excavator hit it.

The lanes were blocked until Department of Transportation snowplows cleared the larger debris from the outside lane so traffic could squeeze past.

Three other vehicles were damaged by running over pieces of concrete or getting hit by the flying debris.

Trooper Dave Bond of the Washington State Patrol said that the driver of the semi-truck would be cited for carrying a load over the legal height. DOT engineers are assessing the structural damage to