

File: 800.12.11.8.12

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[B03]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3014]

 LOCATION SR 395 TYPE EQUIP. IRD Bending Plate

 MP # 27.2 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
11/30/12		NO Changes			
11/21/12		HIGH IMPACT US 395 Both Directions - US 395 Pasco milepost 23: Semi rollover has closed the roadway both directions. A detour is available via local roads. Last Updated: 11/21/2012 6:16 AM At milepost 23 (Tom)			

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[B03]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3014]

LOCATION SR 395 TYPE EQUIP. IRD Bending Plate

MP # 27.2 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
3/31/12		2/14/12 Pasco B03 Patch sensor #5. Found sensor #5 broken on arrival, sensor #6 already disabled in software. Reconfigured class scheme, changed site to loop/loop . Monitored traffic, had Tony call and verify contact. (J. Stack)			
3/31/12		NO Changes			

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [B03]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [3014]</p>
---	--

LOCATION SR 395 TYPE EQUIP. IRD Bending Plate

MP # 27.2 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
2/14/12		<p>2/14/12 Pasco B03</p> <p>Patch sensor #5. Found sensor #5 broken on arrival, sensor #6 already disabled in software. Reconfigured class scheme, changed site to loop/loop. Monitored traffic, had Tony call and verify contact. (J. Stack)</p>			