

File 800.12.11.8.12

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P09]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3019]

 LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

 MP # 121.20 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
11/30/11		No changes			
11/14/11		MODERATE IMPACT I-82 Both Directions - I-82 both directions from milepost 80, near Prosser to milepost 132, Oregon State line: Mobile home restriction due to high winds Last Updated: 11/14/2011 7:09 AM From milepost 80 to milepost 132 (Tom)			

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P09]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3019]

 LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

 MP # 121.20 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
7/31/11		No changes			
7/19/11		7/19/11 Plymouth-P09 Sensor #2 EB on too long. Tested sensor okay. Monitored traffic for about 20 minutes but did not see any problem. (HN)	HN		

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P09]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [3019]</p>
---	--

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 121.20 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
5/4/11		<p>Plymouth-P09 Site inspected. Replaced temperature sensor. Re-spliced loops #1 and #2. Copied log and parameter files. (HN) Called S/C Yakima TMC for a single right lane closure on SR-82 East bound lane # 1 from mile post 119 to mile post 122 @ 0919, phoned into kerri. Set up traffic control and work area. Assisted with installing a new temperature sensor and patching sesors. Put away equipement. Picked up traffic control and cleaned the lane @ 1217. Went to Pasco/SR-395. (Matt H – simms)</p>			

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P09]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [3019]</p>
---	--

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 121.20 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
4/30/11		NO CHANGES			
4/11/11		<p>LOW IMPACT</p> <p>I-82 Both Directions - Interstate 82 between milepost 82, near Prosser to milepost 132, at the Oregon State Line: Monday, April 11, through Thursday, April 14, from 6:30 a.m. to 4 p.m. the Striping Crew will be working both eastbound and westbound. This is a mobile operation allowing traffic to pass freely.</p> <p>From milepost 82 to milepost 132</p> <p>Note***: thundershowers 4/13/11 may cause delays for paint striping (Tom)</p>			

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P09]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [3019]</p>
---	--

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 121.20 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
3/16/11		3/16/11 P09 – Plymouth Met up with Dennis from SC region to pulled in Cat5e cable from the weather station to our cabinet and terminated RJ45 connectors. Installed Moxa serial server # TAZH01107500 with IP: 10.21.166.99 port 4001, Subnet: 255.255.240.0 and Gateway: 10.21.160.1 Removed ZDX modem. Verified contact from shop.	NC		

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P09]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3019]

File: 800.12.11.8.12

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 121.20 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
2/28/11		NO CHANGES			
2/4/11		2/4/2011 1:49:00 PM Both directions milepost 82, near Prosser, to milepost 132, at the Oregon State Line. The transport of mobile homes is restricted due to high winds.			
2/22/11		HIGH IMPACT I-82 Both Directions - Interstate 82 both directions from milepost 82, near Prosser to milepost 132 at the Oregon State Line: The transport of mobile homes is restricted due to high winds. From milepost 82 to milepost 132			