

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
12/31/09		No Changes			

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

 LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

 MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
10/31/09		No Changes			

File: 800.12.11.8.12
533813

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
9/30/09		No Changes			

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P06]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [3813]</p>
---	--

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
8/12/09	(16:00 - 16:35)	Camas-P06 Problem: "Zero axle detected" all lanes. Cleaned and re-seated A/D card. Sensor #5 WB drive lane bad, disabled in software.	(HN)		
8/20/09		P06 Camas Recut sensor # 5, adjusted site parameter. Tried to balance the sensor, but there are not enough trucks and ran out of time, so Hoang will have to do it when he gets back.	(NC)		
8/22/09		State Highway 14 will close early Saturday morning in both directions on the Camas Slough Bridge near milepost 12.8 while maintenance crews inspect the bridge and repair the pavement. Traffic will be rerouted between 5 a.m. and 12 p.m. onto the Highway 14 Business Loop through Camas. On Tuesday, Aug. 25, drivers on Highway 14 through Washougal will encounter a temporary speed limit reduction from 55 miles per hour to 25 mph to allow construction on the pedestrian tunnel project. The project began construction on July 6 and is expected to be complete before the end of the year. For weekly traffic updates visit the Washington State Department of Transportation travel advisory Web site at			

File: 800.12.11.8.12

<p align="center">SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
7/8/09		<p>HIGHEST IMPACT</p> <p>SR 14 Eastbound - Closed to traffic on SR 14 eastbound at MP 14.00 between The Bridge Over Washougal River and Southeast Union Street starting 11:46 AM, 07/08/09 for the next half day -- vehicles with double trailers / wide vehicles</p> <p>From milepost 14 to milepost 15</p> <p>Report Detail</p> <p>Trucks making local deliveries are allowed.</p> <p>Note***: tunnel project at 15th (old SR 140)</p>			

file: 800.12.11.8.12

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
06/01/09		Camas P06 Patched sensor #2 and cut n' cover E/B drive lane.	Jim Stack		

File 800.12.11.8.12
533813

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
2/3/09	(10:00 - 10:45)	Camas-P06 Site inspected. Copied log and parameter files. (HN)	HN		

Scanned