

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P19]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6048]

 LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

 MP # 13.3 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		Out of Study			
11/30/10		No Changes			
11/13/10		<p>Several crashes sent several people to the hospital Saturday night. 11/13/10</p> <p>The most serious happened near Woodinville around 5:38pm. Trooper Keith Leary with the Washington State Patrol said the crash involved a Volkswagen heading eastbound on Hwy 522 near Hwy. 9. The female driver left the roadway on a curve and passed through the median entering oncoming westbound traffic. The Volkswagen began to roll and as it was rolling it was hit by a Chevy Silverado. When the Chevy struck the car the Volkswagen became airborne and was hit again by a Toyota Rav 4.</p> <p>The two occupants of the Toyota and the single occupant of the Chevy were taken to Ferndale Hospital with minor injuries and the driver of the Volkswagen was taken to Harborview Medical Center with multiple critical injuries.</p> <p>Troopers are investigating why the driver left the roadway. There is no indication that alcohol was involved.</p> <p>The posted speed limit in that area is 60mph. (Tom)</p>			

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P19]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6048]

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060[illegible]

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P19]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6048]

 LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

 MP # 13.3 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		Out of Study			
9/1/10	(08:45 09:00)	Problem: Dial, no answer. Found unit #0305-8191 hung up in the boot process. Replaced processor. Had Jim called to verify contact. (HN) Note***: counter had quit 8/27/10 during 9:00am hour (Tom)	HN		
9/14/10		To: Lakey, Ken Subject: Woodinville-P19 Looked like they paved over WB drive lane on midnight September 9th. All class 9 front axle show about 5kips. (HN)	HN		

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P19]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [6048]</p>
---	--

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)MP # 13.3 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		Out of Study			
8/13/10		<p>Did You Feel It? Small Quake In Woodinville Friday Morning It Happened At 6:07 A.M. August 13, 2010 WOODINVILLE - An earthquake was detected early Friday morning near Woodinville. The USGS reports the 2.1 quake hit about 8 miles southeast of Woodinville at about 6:07 a.m. There are no reports of damage. (Tom)</p>			
8/31/10		NO CHANGES			

File: 800.12-11-8.12

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P19]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6048]

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060[illegible]

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P19]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6048]

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060

[illegible]

800.12.11.8.12

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P19]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6048]

LOCATION	SR 522	TYPE EQUIP.	Piezo (Class 1)
----------	--------	-------------	-----------------

MP # 13.3 MODEL # IRD 1060

[illegible]

File: 800.12.11.8.12

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P19]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6048]

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060

[illegible]

800.12.11.8.12

5/7/10		<p>Car broke down on inside shoulder on SR 167 NB just before ramp to I-405 (2:45pm); fire truck blocked HOV lane to check on car. Traffic backed up and resulted in 3 car accident at 180th blocking HOV lane and part of lane 1 (2:50pm). Fire truck from first incident showed up at second incident. Sunshine and blue skies. Incident Response and WSP arrive at 2:54pm. Traffic bailing off to 180th ramp. (Tom)</p> <p>HIGHEST IMPACT SR 167 Northbound - On SR 167 northbound just south of S 180th St there is a collision blocking the HOV lane. At milepost 25</p>	jh		

