



<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
11/2/13	810	On SR 522 westbound at SR 9 Interchange (MP 14) there is a collision partially blocking the ramp. Medical Aid, Fire Assistance, and the State Patrol have arrived on the scene. Cleared 9:15 AM	RH		
11/7/13	828	On SR 522 westbound just west of SR 9 (MP 14) there is a collision blocking the left lane. Medical Aid, Fire Assistance, and the State Patrol have arrived on the scene.  Eastbound & westbound traffic is alternating on SR 92 from 147th Ave NE (MP 4) to Crooked Mile Rd (MP 7) due to roadwork.	RH		
11/13/13		Removed counter kept rebooting itself. Installed new counter.	TN		
11/18/13		Dial, no answer. Found unit hung up in the boot process; Reset counter at site visit.	TN		
11/26/13		Del vol BW ("U"); del axle BW ("U") Counter blanked out 24th. Rebooted itself. default file size on 25th. Replaced processor. Cleaned/re-seated PIO72 card	TN		

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060

[illegible]



<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]	<p>File: 800.12.11.8.12</p>
	*STATE CODE	[ 53 ]	
	*SHRP SECTION ID	[ 6048 ]	

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060[illegible]



File: 800.12.11.8.12

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [ P19 ]</p> <p>*STATE CODE [ 53 ]</p> <p>*SHRP SECTION ID [ 6048 ]</p>
---	--

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)MP # 13.3 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		<b>Out of Study</b>			
01/31/13		<b>No Changes</b>			
01/09/13		1/9/13 Jim found P19 time was off 2 hours and did reset. Looking back at data, it may have happened 11/12/12. Deleted December Data. Will need to delete January 1-9 (Tom)			
01/30/13		<b>1/30/13 P19 Woodinville</b> Piezo #7 WB pass lane not activating. Disabled for now. (HN) Note***: WB Ln 2 went to high errors 12/17/12 (Tom) NOTE***: Jim found time was 2 hours off on 1/9/13 so January data will need to be deleted 1-9; no telling when it started (maybe 11/12/12?)	HOANG		
01/31/13		<b>HIGH IMPACT</b> SR 522 Both Directions - Thursday, Jan. 31 - Both directions of SR 522 remain closed between 164th Street S.E. and Fales/Echo Lakes roads. During the normal 10:15 to 11:15 a.m. rock blasting closure, <b>rock damaged the barrier</b> . The barrier must be removed and replaced before the road can be safely reopened. Drivers will continue using SR 9 as a detour. The highway is expected to reopen at approximately 1 p.m. Last Updated: 1/31/2013 12:12 PM From milepost 23 to milepost 19 (Tom)			