

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P6S)
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

[illegible]

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P6N)
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
1/11/07	(11:30 - 12:45)	P6N Kent Problem: Dial, no answer. Found phone line dead (253) 520-3457 Qwest. Installed switchbox using the South bound phone line for both units. Also found "THEM" chew off the loop harness (loop #5 was broken). Replaced loop harness.	(HN)		