

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P6 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6049 ]

<p align="center">SHEET 15</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P6 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6049 ]

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

[illegible]

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P6 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6049 ]

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

[illegible]



<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [ P6)</p> <p>*STATE CODE [ 53 ]</p> <p>*SHRP SECTION ID [ 6049 ]</p>
---	--

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		<b>OUT OF STUDY</b>			
02/28/13		<b>No Changes</b>			
2/13/13		<p>HIGHEST IMPACT</p> <p>SR 167 Northbound - Update 3:52 PM :On SR 167 northbound just south of SR 516 (MP 20) there is a multi-car collision blocking all lanes. Traffic is getting around on the shoulders. The Incident Response Team and the State Patrol have arrived on the scene.</p> <p>Last Updated: 2/13/2013 3:56 PM</p> <p>At milepost 20 (Tom)</p> <p>***: lanes cleared at 4:30pm</p>			
2/14/13		<p>HIGHEST IMPACT (raining)</p> <p>SR 167 Northbound - Update 9:16 AM : On SR 167 northbound just south of I-405 I/C (MP 26) there is a disabled vehicle blocking the left lane. The State Patrol has arrived on the scene.</p> <p>Last Updated: 2/14/2013 9:17 AM</p> <p>At milepost 26 (Tom)</p>			

[illegible]

File: 800.12.11.8.12

<b>SHEET 15</b> <b>LTPP TRAFFIC DATA</b>  <b>LOG OF CHANGES AT GPS TEST</b> <b>LOCATIONS WITH PERM. AVC OR WIM</b>	*STATE ASSIGNED ID	[ P6)
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6049 ]

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		<b>OUT OF STUDY</b>			
01/31/13		<b>No Changes</b>			
01/09/13		<b>1/9/13 P6 Kent</b> Still having problem connecting and staying connected to site. Contacted Century Link for repair....again.... (HN)			
01/30/13		<b>HIGHEST IMPACT</b> SR 167 Northbound - Update 9:28 AM : On SR 167 northbound just south of I-405 I/C (MP 26) there is a collision blocking the 2 right lanes and part of the HOV lane (pickup between two semi's). The State Patrol has arrived on the scene. Last Updated: 1/30/2013 9:29 AM At milepost 26 (Tom)  Update 10:22 AM : On SR 167 northbound just south of I-405 I/C (MP 26) there is a collision blocking the 2 right lanes. The current backup is 3 miles. Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene.			