

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P32]
	*STATE CODE	[ 53]
	*SHRP SECTION ID	[ A800]

LOCATION Co. Road TYPE EQUIP.

MP # 0.25 on Smith Springs Rd MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
12/11/01		Was: Wrong temp. sensor reading. Action: Rewired temp. sensor ( it was wired wrong). Now: All good data continues.	Rich Rempfer / Hoang Nguyen		<b>9106-1185</b>