

File: 800.12.11.9.12

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P32 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ A800 ]

LOCATION Co. Road TYPE EQUIP. \_\_\_\_\_MP # 0.25 on Smith Springs Rd MODEL # IRD 1068

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
9/30/12		<b>NO CHANGES</b>			
9/10/12		9/10/12 Clyde-P32 Problem: Dial, no answer. Found unit #0305-8190 blanked out. Replaced processor. Had Jim called to verify contact. Note: We had the sensors in the wrong lane! There were 3 trucks going in the opposite direction during the 30 minutes I was there. (HN) Note***: no data from 8/30/12 until site visit 9/10/12 (Tom)			

File: 800.12.11.9.12

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P32]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ A800 ]

LOCATION Co. Road TYPE EQUIP. \_\_\_\_\_

MP # 0.25 on Smith Springs Rd MODEL # IRD 1068

[illegible]